


VM3COP40.13 R-33DE Oxygen Sensor Production Procedure

Parts list		
Qty	Description	Part Number
1	Oxygen sensor – R-33S1	0110132
1	2 pin JST connector	9071014
1	Anti-static gas barrier bag	0150000

Tool list
Soldering iron
Wire cutters
Stanley knife
Small pliers
Solder

Production

- 1) Remove the R-33S1 Oxygen sensor from the gas barrier bag.




- 2) Using a soldering iron, remove the black and red wires.




Revision date: 20-April-2023


- 3) Ensure that the PCB is free from any excess solder or residue.




- 4) Splay the solder contacts to around a 30° angle.



- 5) Place the JST connector on to the PCB, ensuring that the connector contacts align with the contacts of the PCB.




- 6) Solder the two contacts on this side as shown.




- 7) Then turn the sensor around.



- 8) Solder the two contacts on this side as shown.



- 9) This contact here may need bridging with solder.




- 10) Remove the Teledyne label (R-33S1) and replace it with the Vandagraph (R-33DE) label with the same serial number.

NB. To ensure retention of the original serial number, each sensor should be done individually.



QA

- 11) Using the appropriate test lead, connect the sensor to a digital volt meter.



- 12) Set the digital volt meter to the millivolt scale.
- 13) Observe the output of the sensor. The output must be between 23mV and 27mV.
- 14) Using the Intrastats system, mark the sensor as having passed or failed QA as applicable.



Revision date: 20-April-2023

Packing

- 15) Take a sensor that is to be packed, note its serial number, and affix that corresponding bag serial number label to the bag.
- 16) Place the sensor in the bag. Using a strip heat sealer, seal the sensor into the gas barrier bag.
- 17) Once passed, place the finished product, along with the production sheet, on to the production shelf to await stock entry.

