


COMPANY OPERATING PROCEDURES

0018610 BCI P861RA

VM3/COP/32.08.1

Date: 6-Jun-02 Revision date: 17-May-04 Issue: 3











***NB: When there are no service cables available refer to document VM/COP/32.08**



Equipment required: Soldering iron (0060120), solder (0050012), Wire stripper (0060030), Flush Cutter (0060010), Snipe nose pliers (0060021), ‘helping hand’ (0060145), Heat gun (0060100).

Parts list: Kit and parts required. (Continued over page)

D-Type male 9-pin Side			Finger Probe Side		
Qty	Description	Part No.	Qty	Description	Part No.
1	Pre assembled cable	0009564	1	 Top Shell (x25)	0010110
			2	 Pad Support (Orange) (x50)	0010163
			1	 Top Pad (white)(x25)	0010130
			1	 Bottom Pad (white)(x25)	0010131
			1	 Bottom Shell (x25)	0010111
			1	 Spring (x25)	0010140
			2	 Button (Orange) (x50)	0010183
			1	 Detector	0030902

COMPANY OPERATING PROCEDURES

0018610

BCI



P861RA

VM3/COP/32.08.1

Date: 6-Jun-02

Revision date: 17-May-04


Issue: 3

			1		LED/ I.R.	0030953
			1		Strain Relief	0010150

ASSEMBLY OPERATIONS


- 1. Pre Heat soldering iron temperature to 240°c.
- 2. Collect all required parts and equipment listed above.

D-Type male 9-pin side:



- 1. Pre manufactured cable requiring connector to be cut off and ready for probe to be assembled.

Finger Probe side:



COMPANY OPERATING PROCEDURES

0018610

BCI

P861RA

VM3/COP/32.08.1

Date: 6-Jun-02

Revision date: 17-May-04


Issue: 3

1. Apply loctite primer to the cable surface, and slide on the strain relief.
2. Apply a small amount of superglue on to the surface of the cable and push the strain relief over the glue to secure in place leaving approximately 80 mm of cable.
3. Strip outer jacket up to the strain relief and cut packing.
4. Cut wires to 15 mm, strip jackets off 2mm and apply a small amount of solder to the ends.
5. Strip 10 mm off inner jacket and cut off inner shield.
6. Strip jackets 2mm and apply small amount of solder.
7. Solder wires to the detector, LED/I.R as shown in fig 2.3 and solder the orange and blue wires to the outer shield and cover with heat shrink.
8. Place the assembly on the drying rack, and apply a small amount of clear silicon to the front of the detector and LED/I.R and mount into the pads (Led/IR in the top pad and Detector in the bottom pad) allowing the sensors to be seen and central, and scrape excess silicon. Then place the drying rack in the drying cabinet and leave to dry overnight.
9. Superglue loose cable to the pads and fill the rears with white silicon.
10. Glue pads onto the pad supports (prime first).
11. Place spring around pads and into place.
12. Clip upper and lower shells (use a little super glue) into place and glue buttons onto the sides.


TESTING

1. Attach D-Type male 9-pin side to the test box connector marked 'A'.
2. Check display is showing correct characteristics as shown below. (At correct switch positions)

LED should read approx 1.8v



Position 1. IR, LED.



Position 4. Detector

3. If the LED signal is at the bottom then it is wired incorrectly.
4. 'Play' with wire at connections to see if any change in the display (i.e. flickering etc).
5. If there is any movement of signal, the cable must be taken apart and all connections checked and re-soldered. Then tested again until results are satisfactory.
6. Check the cable is of correct quality standard. (See VM/COP/30.11 for details).
7. Attach D-Type male 9-pin side to a 71000A2 monitor and the probe on to the finger to check SpO₂ level. (Ideal reading 95-100.)

COMPANY OPERATING PROCEDURES

0018610

BCI

P861RA

VM3/COP/32.08.1


Date: 6-Jun-02

Revision date: 17-May-04

Issue: 3

Labelling



1. Labels: to be attached facing upwards as looking at the top of the probe.
 - 1 x CE Label
 - 1 x Viamed shell label on probe lower shell.
 - 1 x Serial no. Label
 - 1 x Orange / Brown BCI Label



Quality Assurance (QA)

1. Attach D-Type male 9-pin side to the test box connector marked 'A'.
2. Check display is showing correct characteristics as shown below. (At correct switch positions)

LED should read approx 1.8v



3. If the LED signal is at the bottom then it is wired incorrectly.
4. 'Play' with wire at connections to see if any change in the display (i.e. flickering etc).
5. If there is any movement of signal, the cable must be taken apart and all connections checked and re-soldered. Then tested again until results are satisfactory.
6. Check the cable is of correct quality standard. (See VM/COP/30.11 for details).
7. Attach D-Type male 9-pin side to a 71000A2 monitor and the probe on to the finger to check SpO₂ level. (Ideal reading 95-100.)
8. Fill and sign attached paperwork.

COMPANY OPERATING PROCEDURES

0018610 BCI P861RA

VM3/COP/32.08.1

Date: 6-Jun-02 **Revision date: 17-May-04** Issue: 3

- 9. Test 10 % of batch on DL3000 simulator.
- 10. Log all results on compatibility sheet.

Packaging

- 1. Visually check all labels are attached properly
- 2. Using a twist tie (bunny clip) wrap the cable and place in a small blue Viamed plastic box, ensuring the cable is inserted in a neat and tidy presentable manor.
- 3. Place a serial number sticker (supplied with the batch) on the front face of the box.
- 4. Place a packed and tested sticker (also containing initials of the individual who is packing) on the right hand side top left corner of the box. Do not close box.

Final QA

- 1. Final inspection. Visually ensure cable sit neatly within the box and is in a presentable state.
- 2. Boxes are ready to stock in stores.