


Derek Lamb 33 Outstanding Issues 6 New Issues **Opera** Imported 29/Jul/2008



0110449 - Oxygen sensor, MAX-43. 2 sensor pack.

S/n	Warr. New	Warr. Repair	Status Flag	Repair code	
RE95201007/008	on		Return To Supplier	Low output - During Use	SRN10582 Liverpool Womens Hospital
RE95201005/006	on		Return To Supplier	Low output - During Use	SRN10583 Liverpool Womens Hospital
RE95201011/012	on		Return To Supplier	Non Linear - During Use	SRN10584 Liverpool Womens Hospital
RE95201049/050	on		Return To Supplier	Both cells faulty	SRN11432 Antrim
RE91201017/18	on		Return To Supplier	Both cells faulty	SRN11433 Antrim
SD97101005/006	on		No Fault Found		SRN11456 Royal Liverpool University Hospital
RE91201011/12	on		Return To Supplier	Low output - During Use	SRN12049 Frimley Park Hospital
SH55301039/40	on		Return To Supplier	High output - During Use	SRN12306 Royal Liverpool University Hospital
RG91401005/6	on		Return To Supplier	Low output - During Use	SRN12307 Royal Liverpool University Hospital
RE95201041/042	on		Return To Supplier	Low Output	SRN12783 Medicoline Tekline ApS.
SJ62202011/012	on		Return To Supplier	Both cells faulty	SRN12943 Queen Elizabeth Queen Mother Hospital
SJ62202003/004	on		Return To Supplier	Falling output - During Use	SRN13198 Royal Liverpool University Hospital
SK00101017/018	on		Return To Supplier	No output	SRN13240 Royal Liverpool Univ Hospital
SH55301015/016	on		Return To Supplier	Low Output	SRN13241 Royal Liverpool Univ Hospital
SJ62202013/014	on		Return To Supplier	High output - During Use	SRN13313 Royal Liverpool University Hospital
SM34301065/066	on		Return To Supplier	High no oxygen reading	SRN13314 Royal Liverpool University Hospital

Count of types

Fault Code	Number Failures
Both cells faulty	3
Falling output - During Use	1
High no oxygen reading	1

High output - During Use	2
Low Output	2
Low output - During Use	4
No output	1
Non Linear - During Use	1