



Steve Nixon <steve.nixon.viamed@googlemail.com>

Re: JFD temeprature compensationm deviations

1 message

Steve Nixon <steve.nixon@viamed.co.uk>

11 January 2018 at 13:23

To: "Dumschat, Christa" <Christa.Dumschat@honeywell.com>

Cc: "Lingies, Maik (GE0Y)" <Maik.Lingies@honeywell.com>, Marko Sprössel <marko.sproessel@honeywell.com>, Jessica Wagner <jessica.wagner@honeywell.com>

Thank you Christa, it an excellent and succinct explanation.

JFD are looking into why they set the tolerance even lower than the Teledyne specification. They may have a valid reason or it could be a mistake. Looking at their graphical results, they appear to be using a specification of +/- 4%, I suspect they have misread the Teledyne accuracy specifications at 209 mBar pO2, error min -4, max +4 mBar pO2. So, they have mixed up accuracy specifications numbers with the separate temperature specifications.

In actual field trial use the sensors are performing very well. From experience I do know that the sensors perform well when subject to real dynamic temperature fluctuations.

Regards

Steve

On 11 January 2018 at 11:19, Dumschat, Christa <Christa.Dumschat@honeywell.com> wrote:

Hi Steve,

In our specification, we specify the following:


Effect of Temperature Compensation

(steady state):

Between 0°C and +50°C: 5% relative error

At an pO2 of 205 mbar an error of 10.25 mbar is within the tolerances. The results in your e-mail from 08.12.17 are all within that tolerances (see picture bellow).

Furthermore we specify a warm up time of 30 min. That is the time the sensors need after a sudden change in temperature to reach a stable state. The highest deviation in graph are within that stabilization period.




Hysteresis: we specify the following:

Repeatability: < 1% vol. O₂ @ constant temperature and pressure

In Air (20,95% O₂) a reading from 19,95% O₂ to 21,95 % O₂ is allowed. That are again roughly 10mbar pO2 deviation at ambient pressure. So everything was in specification.

In the results with calibration board only a few points are outside the specification. It is very likely that the resistor on the calibration board interfere with our temperature compensation.



Our sensor and our end test procedure are designed to meet our specification. You can not expect sensor characteristics beyond that.

Regards

Christa

Kind regards / Mit freundlichen Grüßen

i. A. Dr. Christa Dumschat

Chemist R&D

Honeywell | Safety & Productivity Solutions

Intelligent Life Care (ILC)

EnviteC

Office: [+49 3841 360 232](tel:+493841360232)

Fax: [+49 3841 360 222](tel:+493841360222)

Christa.Dumschat@honeywell.com

www.envitec.com

EnviteC-Wismar GmbH a Honeywell Company

Alter Holzhafen 18

23966 Wismar, Germany

Trade Register: Schwerin, HRB 1838

Managing Director: Marcus Ostländer

This message has been scanned for malware.

--
Steve

Steve Nixon
Director - Viamed Ltd.

Office: [+44 \(0\)1535 634542](tel:+44(0)1535634542)

15/01/2018

Gmail - Re: JFD temeprature compensationm deviations

Mobile: [+44 \(0\)7850 252267](tel:+4407850252267)