



Tofo Scuba

 CID9216 Opera **TOFO** Type:**Vandagraph Trade**

Tofo Scuba Praia do Tofo, , Inhambane, , Mozambique

Tel +258 29 329030 GBP Trade Price List Vandagraph (0009)

Proforma Credit Limit 0.00GBP

 Log Call

Add Issue

 Account Home

 Main Details

Account Memos

 Sales History

Stock References

🔄 Cust./Supp. Returns

Service Visits

 Distributor Agreements

Documents
Files

 **Linked Issues**

Regulatory Agreements

SRS68316

SRS Created : 26 Oct 2022

Created By Ryan Swaine

Add Watch

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

ADD
DOCUMENT
TO SRS :
Document
Description

Choose a file to upload: No file chosen

Next

Handle with care

Add Items to Supplier Returns Box

Add

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68316		Notes
Company / Hospital	Tofo Scuba	26/Oct/2022 Ryan Swaine
Contact Name	Ross	26/Oct/2022 Ryan Swaine
Department		VN202 Mk2 - reading low, they have tried various sensors and cables. To test and quote for repair.
Position		23/Nov/2022 Robert Connor
Company Phone	+258 29 329030	Received 1 x VN202 s/n 01355
Direct Phone	00258843733074	03/Jan/2023 Catherine Spence
Opera Account	TOFO	note on order to state we are waiting for a confirmed delivery address
Email	info@tofoscuba.com	17/Jan/2023 Catherine Spence
Order Number		waiting on vandagraph to release to be able to return
Viamed ORD Number		
Date Received Into building	23 Nov 2022	LINKED ISSUE NOTES:
Type	Quote Before Repair	280024:
Issues?	280024	AutoGenerated Issue SRS68316 Appears to be Complete
		09 Dec 2022 Catherine Spence
		ready to send once mail strike has ended

Items for Repair

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN35542	Oxygen Analyser	7910100	 1090560	01355	VN202mkII - Auto Switch	No	No	Complete - Repaired	Low Output	01:00

	VN202				Off			07 Dec 2022 Michael Green		
SRN35542 Engineer Notes: INTERNAL NOTES not for customer discussion 07/Dec/2022 Michael Green The VN202 analyser has been repaired. The sensor input connector and sensor cable have been replaced.										

Currently Viewing ITEM SRN35542 Oxygen Analyser VN202 7910100 01355 VN202mkII - Auto Switch Off

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The VN202 analyser has been repaired. The sensor input connector and sensor cable have been replaced.	07/Dec/2022 Michael Green The VN202 analyser has been repaired. The sensor input connector and sensor cable have been replaced.	The VN202 analyser has been repaired. The sensor input connector and sensor cable have been replaced.

-