

Assessment of cable assemblies from Dolphin Medical Inc : SW & MFG : 03-03-03.

Assessed cable assemblies marked 75-00236-1 REV.X3 & 75-00235-1 REV.X3, noting the following points :-

1. Reverse side of pins are pins (not buckets). Soldering to them is poor but would probably prove reliable.
2. Strain reliefs at either end are a little too stiff and will probably not prevent the cable from breaking just after the strain relief.
3. Only 5 way cable – OK for cable assemblies – need additional conductor for extensions.

Verdict : OK.