

Service Repair Sheet SRS68440

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Daniel Lodge

Royal Liverpool University Hospital

Medical Engineering Department

0151 7062079

0151 706 2000

00002690

daniel.lodge@liverpoolft.nhs.uk

25/Apr/2023

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 14/Apr/2023 Janine Gill

14/Apr/2023 Janine Gill

The customer has an AX300 with the serial number 339155 that keeps showing the alarm sensor and showing zero. Sent SRS number with info to send it to us.

25/Apr/2023 Robert Connor

Received 1 x AX300i s/n 339155, coiled cable s/n 0010470, R-17MED s/n 605862, flow diverter, and 3 x AA battery.

Ready For quote

CCreen 26.4.23

Repair Complete Signed

CCreen 10.5.23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35760	Oxygen Monitor	0111230	339155	222
SRN35761	Oxygen Monitor Cable	0131202	0010470	
SRN35762	Oxygen Sensor	0110017	605862	

0140004 x 1 FOC NO fault found

S/N, SRS, SRN

0140025 x 1 FOC NO fault found.

S/N, SRS, SRN

~~0140012~~ x 1 -> change to 0140016. cg 10.5.23

~~210~~ S/N, SRS, SRN


0110017 x 1 @ £53.00 REMOVE cg 10.5.23

SRS, SRN

25 x 1 @ £12. Turn to £0 as free of charge repair

68440

ed Ltd



Daniel Lodge

0151 706 2079

Royal Liverpool Hospital,

Mount Vernon Street,

Liverpool,

L7 8YE

tals NHSFT

Lane

Contact Name

Contact Tel

: Daniel Lodge

: 01517062079

Account

00002690

Customer Reference

SRS68440

Date

27 Apr 2023

Priority

: 7

Valid until

: 28 May 2023

Page 1

al Liverpool Uni Hospital, UK * Incoterms® 2020

ths@viamed.co.uk

Alarming ✓ Sensor

won't show readings

changed sensor however still
alarming

Quantity	£ Unit	£ Unit Vat	£ Total
1	0.00	0.00	0.00

1	0.00	0.00	0.00
---	------	------	------

SRS68440, SRS68440, SRN35761

No fault found

0140012

Oxygen sensor evaluation.

1	0.00	0.00	0.00
---	------	------	------

S/N: 605862, SRS68440, SRN35762

0110017

Teledyne Sensor R-17MED

1	53.00	10.60	63.60
---	-------	-------	-------

SRS68440, SRN35762

PPUPS1

UPS Courier Delivery - Standard

1	12.00	2.40	14.40
---	-------	------	-------

Total Net: £ 65.00

Total Vat: £ 13.00

Total: £ 78.00

Banking details

Bank

Sort Code

Account Number

IBAN

BIC

Terms and conditions <https://www.viamed.co.uk/terms>

BIC

Barclays Bank PLC

20-78-42

00906662

GB05BUKB20784200906662

BUKBGB22

Terms: Net 30 days from date of invoice.

Full invoice amount to be credited to our account net of all bank charges.

Claims: Please claim non delivery within 7 days of invoice.

Shortages or damage within 3 days of receipt.

Claims after these times cannot be entertained.

Title to goods does not pass until payment in full has been received.

Service Repair Sheet 68440

Contact Name

Daniel Lodge

Company/ Hospital Name

Royal Liverpool University Hospital

Department

Medical Engineering Department

Direct Phone

0151 7062079

General Phone

0151 706 2000

Opera Account

00002690

Email

daniel.lodge@liverpoolft.nhs.uk

Date Received

25/Apr/2023

Booked in By

Robert Connor

Repair	Ref	S/N	Equipment Type
SRN35760	0111230	339155	Oxygen Monitor

No Fault Found
Time :0 Hour(s)

The monitor is working well.

Repair	Ref	S/N	Equipment Type
SRN35761	0131202	0010470	Oxygen Monitor Cable

No Fault Found
Time :0 Hour(s)

No fault found

Repair	Ref	S/N	Equipment Type
SRN35762	0110017	605862	Oxygen Sensor

Declined Repair
Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017

This sensor is dead. The replacement is not needed by the customer.
