



Work Instructions & Test Methods

Final Quality Assurance is carried out in Viamed.

All probes

1. visually inspected
2. diodes and resistors checked.
3. Boxed
4. labelled
5. Insert added

One sample of each type and each batch are fully tested for "R" curve on DL3000 and the original manufacturers instrument.

The basic probes can have the instrument connector changed in line with the Repair facility procedures so that they can be used on other types of equipment.

For Latest Viamed Work Instructions & procedures See
Procedure Files ISO9001/EN46001