

MG Half , CS Half , EH Full



Narked at 90

 CID5875 Opera V001065 Type:Vandagraph Trade

Marked at 90 15 Bentley Court, Paterson Road, Wellingborough, , NN8 4BQ, UK

Tel **01933 681 255** GBP Trade Price List Vandagraph (0009)



Add Issue

Credit 30 Days after date of invoice Credit Limit 0.00GBP

 Account Home

 Main Details

Account Memos

 Sales History

Stock References

⦿ Cust./Supp. Returns

 Service
Visits

Distributor Agreements

Documents
Files

 **Linked Issues**

Regulatory Agreements

SRS68527

SRS Created : 25 Jul 2023

Created By Robert Connor

Add Watch

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

Handle with care

Add Items to Supplier Returns Box

Add

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Add Notes

Service Repair Sheet 68527 SELECT * FROM viamedquoteaddress where ID='5875'		Notes 25/Jul/2023 Robert Connor 25/Jul/2023 Robert Connor Received 1 x R22VAN s/n 102728 25/Jul/2023 Catherine Spence in Vandagraph room 09/Aug/2023 Catherine Spence in engineers room LINKED ISSUE NOTES: 303706: AutoGenerated Issue SRS68527 Appears to be Complete
Company / Hospital	Narked at 90	
Contact Name	John Routley	14 Aug 2023 Catherine Spence with vandagraph
Department		
Position	Director	
Company Phone	01933 681 255	
Direct Phone	01933 681255	
Opera Account	V001065	
Email	john@narkedat90.co.uk	
Order Number		
Viamed ORD Number		
Date Received Into building	25 Jul 2023	
Type	Warranty	
Issues?	303706	

Items for Repair

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
-----	-----------	-----------------	---------	--------------	-------------	--------------	-----------------	--------	-------------	------------

11/09/2023, 13:20

SRS View

SRN35936	Oxygen Sensor Vandagraph	0110232 Requires Service Manual Linking in System	 2152515	102728	Oxygen Sensor R-22VAN	Yes	No	No Fault Found 11 Aug 2023 Michael Green	No Fault Found	00:00
SRN35936 Engineer Notes: INTERNAL NOTES not for customer discussion 27/Jul/2023 Michael Green The R-22VAN Oxygen sensor has been tested. The output in air was 10.6mV. The output in Oxygen was 51.0mV. No fault was found with the sensor.										

Currently Viewing ITEM SRN35936 Oxygen Sensor Vandagraph 0110232 102728 Oxygen Sensor R-22VAN

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The R-22VAN Oxygen sensor has been tested. No fault was found with the sensor.	27/Jul/2023 Michael Green The R-22VAN Oxygen sensor has been tested. The output in air was 10.6mV. The output in Oxygen was 51.0mV. No fault was found with the sensor.	The R-22VAN Oxygen sensor has been tested. No fault was found with the sensor.

-