

Service Repair Sheet SRS68590

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Sara Walsh

Gama Aviation Plc

Clinical Service Manager

01202 013687

01252 553029

CID19740

sara.walsh@gamaaviation.com

04/Oct/2023

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☒

Signed: RS
Date: 4/10/23

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes 02/Oct/2023 Steve Hardaker

02/Oct/2023 Steve Hardaker

Returning a MaxBlend 2 for overhaul service. Service kit is in stock, R200P02.

04/Oct/2023 Robert Connor

Received 1 x maxblend s/n FA56833001, with MAX-550E s/n HH82199025, with flow diverter and sensor cable.

Ready For quote

C Green 11-10-23

Repair Complete Signed

C Green 17-11-23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36057	Blender	0310291	FA56833001	<u>NO</u>
SRN36058	Oxygen Sensor	0110452	HH82199025	Yes

0380061 x 1 @ E180
S/N, SRS, SRN

R200P02 x 1 @ E270
SRS, SRN

UPS x 1 @ E12

-> 0140011 x 1 FOC
S/N, SRS, SRN

UPS x 1 @ E12

Service Repair Sheet 68590

Contact Name

Company/ Hospital Name

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Sara Walsh

Gama Aviation Plc

Clinical Service Manager

01202 013687

01252 553029

CID19740

sara.walsh@gamaaviation.com

payment recd, no PO

04/Oct/2023

Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN36057	0310291	FA56833001	Blender	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 0380061

Qty: 1 R200P02

Blender FA56833001 has been stripped and ultrasonically cleaned. It has been rebuilt, using the service kit, and tested as per the service manual.

Repair	Ref	S/N	Equipment Type		Under Warranty
SRN36058	0110452	HH82199025	Oxygen Sensor	No Fault Found Time :0 Hour(s)	
