

## Ryan Swaine <viamed.ryan.swaine@gmail.com>

## Re: RFQ - Sensors compatible with P/N: 9100-9212-5H

1 message

**Umer Khan** <umer@utooffshore.com> To: ryan.swaine@vandagraph.co.uk

6 December 2023 at 09:53

HI Ryan,

Please find attached payment advise for GBP 795. Kindly provide us with 2 X R-33VAN instead of 1 nos as requested earlier.

Regards,

UTO"

Umer Khan / Usha Trading & Offshore LLC

Manager - Business Operations

e: umer@utooffshore.com m: +971 (0)50.954.2167

**Disclaimer:** This e-mail and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this E-mail in error, or you do not wish to receive further e-mails, please notify the sender by E-mail. Any views or opinions expressed are solely those of the author and do not necessarily represent those of Usha Trading & Offshore LLC. No binding contract will result from this email until such time as a written document is signed on behalf of the company. The recipient should check this e-mail and any attachments for the presence of viruses. The company accepts no liability for any damage caused by any virus transmitted by this e-mail. *Please consider the environment before printing this email.* 

On 22-Sep-2023, at 8:14 PM, Ryan Swaine <office@viamed.co.uk> wrote:

Hi Umer

Understood. R-33VAN = GBP £40 each EXW

Best regards Ryan

Ryan Swaine General Manager VANDAGRAPH Ltd.

http://www.vandagraph.co.uk

Email ryan.swaine@vandagraph.co.uk

Tel: +44 (0)1535 634900 Mob: +44 (0)7803 907117

On Fri, 22 Sept 2023 at 15:18, Umer Khan <umer@utooffshore.com> wrote:

Hi Ryan,

I believe the cost of logistics to send and Analyser on a returnable basis to UK will not be feasible.

We would instead order 1 to test at our end in our device and then can come back to you if successful for more quantity.

Can you please quote for 1 sensor.

Regards,

Umer

On Fri, Sep 22, 2023, 7:36 PM Ryan Swaine <office@viamed.co.uk> wrote: Dear Umer

Thank you very much for your email and message.

I believe that either our R-33VAN or R-33VAN(RP) would be a suitable replacement sensor, but I can not confirm this, as we have never tested it with a device.

The R-33VAN and R-33VAN(RP) are the same sensor, but the connector is wired the opposite way. They can be switched very easily.

If you have a spare device we can borrow to test a sensor then we could confirm this for you.

With regards to the R-33VAN-2, we can supply you at our trade price of GBP £65 each EXW. These sensors are assembled to order, the lead time is typically 1-2 weeks from receipt of order/payment.

Please let me know if you have any questions or concerns.

Best regards Ryan

Ryan Swaine General Manager VANDAGRAPH Ltd. http://www.vandagraph.co.uk

Email ryan.swaine@vandagraph.co.uk

Tel: +44 (0)1535 634900 Mob: +44 (0)7803 907117

On Fri, 22 Sept 2023 at 12:40, Umer Khan <umer@utooffshore.com> wrote: Hello.

We are looking for sensors that are compatible with P/N: 9100-9212-5H

Please let us know if you have any sensor which are compatible with the same.

Further, we also require 11 nos of R-33VAN-2.

The delivery address shall be as below: Usha Trading & Offshore LLC Sharjah Media City Sharjah, UAE

Regards,

"UTO"

Umer Khan / Usha Trading & Offshore LLC

Manager - Business Operations

**e:** <u>umer@utooffshore.com</u> **m:** +971 (0)50.954.2167

**Disclaimer:** This e-mail and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this E-mail in error, or you do not wish to receive further e-mails, please notify the sender by E-mail. Any views or opinions expressed are solely those of the author and do not necessarily represent those of Usha Trading & Offshore LLC. No binding contract will result from this email until such time as a written document is signed on behalf of the company. The recipient should check this e-mail and any attachments for the presence of viruses. The company accepts no liability for any damage caused by any virus transmitted by this e-mail.

Please consider the environment before printing this email.

