

Tofo Scuba

CID9216 Opera **TOFO** Type:Vandagraph Trade

Tofo Scuba Praia do Tofo, , Inhambane, , Mozambique

Tel **+258 29 329030** GBP Trade Price List Vandagraph (0009)

Log Call

Add Issue

Proforma Credit Limit 0.00GBP

Account Home

Main Details

Account Memos

Sales History

Stock References

Cust./Supp. Returns

Service Visits

Distributor Agreements

Documents Files

Linked Issues

Regulatory Agreements

SRS68775

SRS Created : 09 May 2024
Created By Ryan Swaine
Add Watch

[Print Barcodes](#)
[Print A4 Sheet](#)
[Split Items into Different SRS Numbers](#)
[Edit Details](#)

Handle with care

Add Items to Supplier Returns Box

Add

- ☐ Return for Credit / Return to Stock
- Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description

Choose a file to upload:

Choose file

 No file chosen

Next

Service Repair Sheet 68775		Notes 09/May/2024 Ryan Swaine 09/May/2024 Ryan Swaine Vandagraph O2 analyser for service. Has an error on the display 15/May/2024 Robert Connor Received 1 x VN202 s/n 00770
Company / Hospital	Tofo Scuba	
Contact Name	Ross	
Department		
Position		
Company Phone	+258 29 329030	
Direct Phone	00258843733074	
Opera Account	TOFO	
Email	info@tofoscuba.com	
Order Number		
Viamed ORD Number		
Date Received Into building	15 May 2024	
Type	Quote Before Repair Move to Repair	
Issues?		

Items for Repair

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN36448	Oxygen Analyser	7910100 Requires	870797	00770	VN202mkII - Auto Switch	No	No	Unfinished		00:00

20/05/2024, 09:38

SRS View

	VN202	Service Manual Linking in System			Off					
SRN36448 Engineer Notes: INTERNAL NOTES not for customer discussion 16/May/2024 Michael Green The VN202 analyser has been tested. The unit is showing E1. There is corrosion on the battery contacts and sensor input connector. If these parts are corroded, then it would be advisable to replaced the wiring harness.										

Currently Viewing ITEM SRN36448 Oxygen Analyser VN202 7910100 00770 VN202mkII - Auto Switch Off

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	16/May/2024 Michael Green The VN202 analyser has been tested. The unit is showing E1. There is corrosion on the battery contacts and sensor input connector. If these parts are corroded, then it would be advisable to replaced the wiring harness.	Non added Yet

-

ISO REVIEW

Please Select

Instructions