

Service Repair Sheet 68763

| | |
|------------------------|--|
| Contact Name | Ros Rochester |
| Company/ Hospital Name | Worcester Royal / Siemens Healthcare |
| General Phone | 01905733176 |
| Opera Account | 00005446 |
| Email | ros.rochester@siemens-healthineers.com |
| Order Number | 4515208089 |
| Date Received | 29/Apr/2024 |
| Booked in By | Robert Connor |

| | | | | |
|----------|---------|--------|----------------|--|
| Repair | Ref | S/N | Equipment Type | |
| SRN36397 | 0111235 | 312948 | Oxygen Monitor | Complete - Repaired Time :0.5 Hour(s) |

Parts Replaced

| | |
|----------|---------|
| Qty: 1 | 0131214 |
| Qty: 0.5 | 0140005 |

The MX300 Oxygen monitor has been repaired. The sensor input connector has been replaced.

| | | | | |
|----------|---------|------|----------------------|--------------------------------|
| Repair | Ref | S/N | Equipment Type | |
| SRN36398 | 0131201 | 2063 | Oxygen Monitor Cable | Written Off Time :0 Hour(s) |

Parts Replaced

| | |
|--------|---------|
| Qty: 1 | 0131201 |
|--------|---------|

The sensor cable has been replaced with SN:5694.

| | | | | |
|----------|---------|--------|----------------|-----------------------------------|
| Repair | Ref | S/N | Equipment Type | |
| SRN36399 | 0110017 | 605825 | Oxygen Sensor | No Fault Found Time :0 Hour(s) |

The R-17MED Oxygen sensor has been tested. The sensor is working within specification.