

Ryan Swaine [Required Reading](#) 1 Issues | [My Requests](#) 18.60 °C

Contacts

Search

Tofo Scuba

CID9216 Opera **TOFO** Type:**Vandagraph Trade**

Tofo Scuba Praia do Tofo, , Inhambane, , Mozambique

Tel **+258 29 329030** GBP Trade Price List Vandagraph (0009)

Proforma Credit Limit 0.00GBP

Log Call

Add Issue

Account Home

Main Details

Account Memos

Sales History

Stock References

Cust./Supp. Returns

Service Visits

Distributor Agreements

Documents Files

Linked Issues

Regulatory Agreements

SRS68943

SRS Created : 30 Oct 2024
Created By Ryan Swaine
Add Watch

- [Print Barcodes](#)
- [Print A4 Sheet](#)
- [Split Items into Different SRS Numbers](#)
- [Edit Details](#)

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock

Unopened - will apply to all items on srs

☐ Clear From System - Force from System. -

will apply to all items on srs

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description

Choose a file to upload:

Choose file

 No file chosen

Next

Add notes to SRS

Add Notes

Service Repair Sheet 68943

Company / Hospital	Tofo Scuba
Contact Name	Ross
Department	
Position	
Company Phone	+258 29 329030
Direct Phone	00258843733074
Opera Account	TOFO
Email	info@tofoscuba.com
Order Number	
Viamed ORD Number	
Date Received Into building	12 Nov 2024
Type	Quote Before Repair Move to Repair
Issues?	

Notes

30/Oct/2024 Ryan Swaine

30/Oct/2024 Ryan Swaine
VN202 with a potential corrosion issue. To test and quote for repair.
12/Nov/2024 Robert Connor
Received 1 x VN202 s/n 01355.
15/Nov/2024 Catherine Spence
Engineers Room
06/Dec/2024 Catherine Spence
Engineers room waiting on ryan
24/Dec/2024 Catherine Spence
still with engineer

Items for Repair

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN37189	Oxygen Analyser	7910100 Requires	 1090560	01355	VN202mkII - Auto Switch	No	No	Unfinished		00:00

07/01/2025, 17:35

SRS View

	VN202	Service Manual Linking in System			Off					
SRN37189 Engineer Notes: INTERNAL NOTES not for customer discussion 18/Nov/2024 Michael Green The VN202mk2 has been tested and given an internal inspection. The unit has a scruffy case, but it is working as expected. No signs of corrosion were found. No sensor cable or sensor were supplied with the analyser.										

Currently Viewing ITEM SRN37189 Oxygen Analyser VN202 7910100 01355 VN202mkII - Auto Switch Off

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	18/Nov/2024 Michael Green The VN202mk2 has been tested and given an internal inspection. The unit has a scruffy case, but it is working as expected. No signs of corrosion were found. No sensor cable or sensor were supplied with the analyser.	Non added Yet

ISO REVIEW

Please Select

Instructions