



OPM (Labels & Packaging) Group Ltd
The Colour Box, Gelderd Road
Leeds, West Yorkshire, LS12 6TG
Tel: +44 (0) 113 2311000 Fax: +44 (0) 113 2630609

Your Label and Packaging Partner

www.opmgroup.co.uk



Deliver To:

Purchasing

Viamed Ltd

15 Station Road
Cross Hills
Keighley
West Yorkshire
BD20 7DT

Despatch Advice

EMAIL

Delivery No: 195497
Our Ref: 345437
Your Ref: PVM4299
Date Out: 05/03/2025
Delivery Date: **05/03/2025**
Method of Despatch: OPM
Service:
No. of Parcels: 2 boxes

Code	Description	Job No	Quantity Ordered	Quantity Delivered	To Follow
9992523	Automotive Oxygen Sensor	345437	5,000	5,000	

Your order ref PVM4299 has been despatched as per above.

Your goods will be delivered to you on the date stated. If you do not receive your order please feel free to contact our Customer Services Team on **0113 263 0609** or email us at Hugh.moran@opmgroup.co.uk

Certificate of Conformity

This Certificate of Conformity certifies that the whole of the product(s) detailed hereon have been manufactured, inspected and tested to the agreed specification, in accordance with the quality systems requirements of BS EN ISO 9001:2015
Full traceability of the product, with all its components, process and quality data is available through OPM Group.

Delivery No: 195497
Our Ref: 345437
Your Ref: PVM4299
Date Out: 05/03/2025

STORAGE, HANDLING & APPLICATION

1. STORAGE

For optimal storage conditions, maintain a cool, dry environment with temperatures ranging between 20 to 25°C and a relative humidity of 40-50%.
Stack reels vertically to prevent distortion of the core.
Store the items in cardboard boxes until they are ready for use, and ensure they are shielded from direct sunlight.
To manage inventory effectively, rotate stocks regularly, prioritizing the use of the oldest items first.
When required, repackage partially used reels into their original packaging for secure storage.

2. HANDLING

Remember all reels are most vulnerable on edges so handle gently.
Rough handling can cause 'nicking' and eventual web break on applicator machines.

3. APPLICATION

The following is a list of surfaces to which it is difficult to obtain satisfactory adhesion :
P.I.F.E., untreated polygelatins, silicone treated or contaminated surfaces,
surfaces chemically treated, waxed surfaces, printed polyethylene, rough surfaces,
ie: wood, metal, weaved fabric, moist or cold surfaces, surfaces with condensate bloom,
irregular shaped surfaces, dusty surfaces, surfaces where adhesive may be significantly exposed to atmosphere.