Service Repair Sheet 69007

Contact Name Mr Mahesha

Company/ Hospital Name BDI India Private Limited Department Customer Support Oustomer Support Position Plane 918022560418 General Phone 918022560418 Opera Account 00006454

Email mahesha@bdi-india.com

Date Received 05/Mar/2025 Booked in By Robert Connor

Repair Ref S/N Equipment Type

SRN37669 1410000 PR02529A11 Foetal Simulator Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309 Qty: 1 1430288

V1000 has had transducer interface cushion and battery contacts replaced, calibration has been checked.

Repair Ref S/N Equipment Type SRN37670 1410000 PR02529A14 Foetal Simulator

RN37670 1410000 PR02529A14 Foetal Simulator Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair Ref S/N Equipment Type

SRN37671 1410000 PR02529A15 Foetal Simulator Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair Ref S/N Equipment Type

SRN37672 1410000 PR02529A17 Foetal Simulator Complete - Repaired

Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309 Qty: 1 1430288

V1000 has had transducer interface cushion and battery contacts replaced, calibration has been checked.

Service Repair Sheet 69007

Contact Name Mr Mahesha

Company/ Hospital Name BDI India Private Limited Department Customer Support Oustomer Support Position Plane 918022560418 General Phone 918022560418 Opera Account 00006454

Email mahesha@bdi-india.com

Date Received 05/Mar/2025 Booked in By Robert Connor

Repair Ref S/N Equipment Type

SRN37673 1410000 PR02529A18 Foetal Simulator Complete - Repaired

Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair Ref S/N Equipment Type

SRN37674 1410000 PR02529A20 Foetal Simulator Complete - Repaired

Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair Ref S/N Equipment Type

SRN37675 1410000 PR02529A22 Foetal Simulator Complete - Repaired

Time: 0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair Ref S/N Equipment Type

SRN37676 1410000 PR02380A12 Foetal Simulator Complete - Repaired

Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Service Repair Sheet 69007

Contact Name Mr Mahesha

Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account

BDI India Private Limited
Customer Support
Customer Support
918022560418
918022560418
00006454

Email mahesha@bdi-india.com

Date Received 05/Mar/2025 Booked in By Robert Connor

Repair Ref S/N Equipment Type

SRN37677 1410000 PR02540A13 Foetal Simulator Complete - Repaired

Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309 Qty: 1 1430288

V1000 has had transducer interface cushion and battery contacts replaced, calibration has been checked.

Repair Ref S/N Equipment Type SRN37678 1410000 PR02540A14 Foetal Simulator Complete - Repaired

Time: 0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.