

PC 09:00:00 AM For 1 Hours



**Pinguim Sub
LDA**

CID4028 Opera PINGUIM Type:Vandagraph Trade
Pinguim Sub LDA Urb. Da Raminha Lote 1, , Portimao, , 8500-579, Portugal
Tel **+35 1282485784** GBP Trade Price List Vandagraph (0009) Log Call

Add Issue

Credit 30 Days after date of invoice Credit Limit 0.00GBP
VAT PT503017876

- Account Home

Main Details

Account Memos

Sales History

Stock References

Cust./Supp. Returns

Service Visits

Distributor Agreements

Documents Files

Linked Issues

Regulatory Agreements

SRS68962

SRS Created : 14 Nov 2024
Created By Michael Lamb
Add Watch

- [Print Barcodes](#)
[Print A4 Sheet](#)
[Split Items into Different SRS Numbers](#)
[Edit Details](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description

Choose a file to upload:

Choose file

No file chosen

Next

Handle with care
Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs

☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68962		Notes
Company / Hospital	Pinguim Sub LDA	14/Nov/2024 Michael Lamb
Contact Name	Joao Paulo Rosario	14/Nov/2024 Michael Lamb
Department		Returning mixcheck with broken display,
Position	Accounts	Unknown S/N
Company Phone	+35 1282485784	To be sent back to a UK address, pending customer reply
Direct Phone	00351917209235	19/May/2025 Robert Connor
Opera Account	PINGUIM	Received Received 1 x mixchek s/n 277932
Email	joao.rosario@pinguimsub.pt	22/May/2025 Ryan Swaine
Order Number		RS to email when it is ready, as they would like to add some sensor to shipment 04/Jun/2025 Catherine Spence
Viamed ORD Number		With Engineer
Date Received Into building	19 May 2025	
Type	Quote Before Repair Move to Repair	
Issues?	367318	
Items for Repair		
		LINKED ISSUE NOTES: 367318: AutoGenerated Issue SRS68962 Appears to be Complete

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN37876	MixChek	MIXCHEK Requires Service Manual Linking in System	 298421	277932	Mixchek	No	No	Complete - Repaired 17 Jun 2025 Michael Green	Display fault	01:30
SRN37876 Engineer Notes: INTERNAL NOTES not for customer discussion 17/Jun/2025 Michael Green The Mixchek analyser has been repaired. The Oxygen display and gas sample tubing have been replaced. The fitted Oxygen sensor was dated H8. A new one has not been fitted, as requested.										

Currently Viewing ITEM SRN37876 MixChek MIXCHEK 277932 Mixchek

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Mixchek analyser has been repaired. The Oxygen display and gas sample tubing have been replaced. The fitted Oxygen sensor was dated H8. A new one has not been fitted, as requested.	17/Jun/2025 Michael Green The Mixchek analyser has been repaired. The Oxygen display and gas sample tubing have been replaced. The fitted Oxygen sensor was dated H8. A new one has not been fitted, as requested.	The Mixchek analyser has been repaired. The Oxygen display and gas sample tubing have been replaced. The fitted Oxygen sensor was dated H8. A new one has not been fitted, as requested.

ISO REVIEW

Please Select

Instructions