Service Repair Sheet 69120

Contact Name Mr Mahesha

Company/ Hospital Name BDI India Private Limited Department Customer Support Customer Support Direct Phone 918022560418 General Phone 918022560418 Opera Account 00006454

Email mahesha@bdi-india.com

Date Received 12/May/2025 Booked in By Robert Connor

Repair Ref S/N Equipment Type

SRN37848 1410000 PR02529A10 Foetal Simulator Complete - Repaired

Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair Ref S/N Equipment Type

SRN37849 1410000 PR02529A12 Foetal Simulator Complete - Repaired

Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair Ref S/N Equipment Type
SRN37850 1410000 PR02380A14 Foetal Simulator Co

RN37850 1410000 PR02380A14 Foetal Simulator Complete - Repaired Time :0 Hour(s)

Time to Hour(s

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair Ref S/N Equipment Type

SRN37851 1410000 PR02529A24 Foetal Simulator Complete - Repaired

Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Service Repair Sheet 69120

Contact Name Mr Mahesha

Company/ Hospital Name
Department
Customer Support
Customer Support
Direct Phone
General Phone
Opera Account

BDI India Private Limited
Customer Support
918022560418
918022560418
00006454

Email mahesha@bdi-india.com

Date Received 12/May/2025 Booked in By Robert Connor

Repair Ref S/N Equipment Type

SRN37852 1410000 PR02540A12 Foetal Simulator Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.