



# Goods In Procedure 8010007 NaNS01 Oxygen Sensor



v1.1 25<sup>th</sup> June 2017



### 1. Verify sensor model

Using the images below verify that the sensors are the correct model, in terms of casing, connector.

Image to be added






#### 2. Verify labelling

Using the images below verify that the sensor and oxygen senor bag labels are correct.

- a) Check that the serial numbers follow on from the last batch.
- b) Serial number format: S011xxxxx
- c) Check date format and that it is current and valid: Year-Month, e.g. 2011-05 NOTE: we may have stipulated a 'manufactured' month required on the purchase order.

Oxygen sensor label 90.0mm x 15.0mm

White vinyl label, text & graphics – black




## Andagraph Sensor Technologies



Gas barrier bag label 63.5mm x 46.6mm

White label, text & graphics – black



**NOTE**: Check that the there is a 'breathing hole' through the label and bag.

#### 3. Sensor test results

Ensure that the factory production test results have been received in spreadsheet format and save a copy in **Z** drive, within the folder: **VST Sensor Test Results Sheets**.

#### 4. Processing of the Purchase Order

Check the received paperwork against the purchase order and process in Opera following standard procedures.

#### 5. Book-in sensors into Intrastats

- a) Check serial number run and input into Intrastats.
- b) Print off A4 sheet/s with bar code labels.



### 6. Sealing and bar code label

a) Check that the single line heat seal is intact. Using the heat seal machine (with wide security seal band), re-seal the bag over the existing single line seal, see image below.



Generic pictures for illustration purposes only.

## 7. Packing

- a) Together with the A4 sheets printed with bar code labels, scan to and store sensors (in serial number order) in a labelled large plastic storage bin in the VST stock area.
- b) Assemble packing box/es. (Instructions & images to be inserted)
- c) Affix packing box labels.
- d) Pack the sensors into the packing box (instructions & images to be inserted)
- e) Insert the A4 sheet's with bar code labels into the top of the packing box.
- f) Insert Declaration of Conformity Certificate (if applicable, need to state for each sensor.
- g) Loosely seal the packing box and then scan to store in the VST stock area.

### 8. Shipping

- a) As appropriate, scan the sensors to the order using the A4 sheet/s with the bar code labels. Then discard the A4 sheets/s.
- b) Insert a copy of the invoice (if applicable).
- c) Depending upon sensor quantities, multiple boxes may need to be packed into a large cut down box, depends upon each customer usual or requested quantities.
- d) Affix UPS shipping labels.