

Engineering Change Order Number: MS Mk3/001.

Author: Peter Anderson.
Date: 26th October 2004.

Problem.

The reverse battery protection diode, D1, is failing open circuit due to excessive pulse currents.

Curative action.

Change the 1N4148 diode to a BAV21 diode. This has higher ratings but is in the same package format.

Implementation.

New diode is to be fitted in production.