



: 33138 ? 67597 :

[Print Barcodes](#)[Dymo \(Testing\)](#)[Print A4 Sheet](#)[Split Items into Different SRS Numbers](#)[Attach Customer Letter](#)

Add Items to Supplier Returns Box

Handle with care

☐ Return for Credit / Return to Stock Unopened - will apply to all items on srs☐ Clear From System - Force from System. - will apply to all items on srs

Add Add notes to SRS

Add Notes

Service Repair Sheet 67597

Company / Hospital	Carsten Kuhlisch
Contact Name	
Department	
Position	
Company Phone	+49 7751700788
Direct Phone	
Opera Account	CID15683
Email	mekkij@icloud.com
Order Number	
Viamed ORD Number	
Date Received Into building	02 Oct 2020
Type	Quote Before Repair
Issues?	199872

Notes

22/Sep/2020 Ryan Swaine

22/Sep/2020 Ryan Swaine

22/Sep/2020 Ryan Swaine

MixChek - Requires Calibration and testing. quote for any repairs required. Reading low, so may have a tubing leak.

LINKED ISSUE NOTES:[199872:](#)

AutoGenerated Issue SRS67597 Appears to be Complete

Items for Repair

SRN	Equipment	Stock Reference	Serialnumber Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN33138	MixChek			306655		No	No	Complete - Repaired	Calibration Problem	01:00

Currently Viewing ITEM SRN33138 MixChek 306655[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Mixchek analyser has been calibrated. The Helium output now reads correctly. The Oxygen sensor has been tested. The gas sample tubing has been replaced.	07/Oct/2020 Michael Green The Mixchek analyser has been calibrated. The Helium output now reads correctly. The Oxygen sensor has been tested. The gas sample tubing has been replaced.	The Mixchek analyser has been calibrated. The Helium output now reads correctly. The Oxygen sensor has been tested. The gas sample tubing has been replaced.