Service Repair Sheet SRS67877

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Francis Loch

Forth Valley Royal Hospital

Medical Physics

Specialist Clinical Technologist

01324 566 956

00004880

francis.loch@nhs.scot

30/Jun/2021

Robert Connor

Viamed

Warranty

Notes 28/Jun/2021 Steve Hardaker 28/Jun/2021 Steve Hardaker 28/Jun/2021 Steve Hardaker

Returning 3x 0110705 MLF-19 s/n 100059, 100060 & 100061 that have the wrong connector and looks like the wrong sensor body: it has a 3-pin Molex (see attached). It would make more sense that this is actually a different sensor with the wrong label applied.

Please check our stock before replacing; the customer is happy if we have to send the replacements in sealed bags

instead of cans.

Added issue 227149 to SN to report to manufacturer.

30/Jun/2021 Catherine Spence

Stock that we have has been checked and is correct

30/Jun/2021 Steve Hardaker

28/Jun/2021 Steve Hardaker

28/Jun/2021 Steve Hardaker

28/Jun/2021 Steve Hardaker

Returning 3x 0110705 MLF-19 s/n 100059, 100060 & 100061 that have the wrong connector and looks like the wrong sensor body: it has a 3-pin Molex (see attached). It would make more sense that this is actually a different sensor with the wrong label applied.

Please check our stock before replacing; the customer is happy if we have to send the replacements in sealed bags instead of cans.

Added issue 227149 to SN to report to manufacturer. 30/Jun/2021 Catherine Spence Stock that we have has been checked and is correct Francis has shipped the sensors back by TNT, ref 244536518. 30/Jun/2021 Robert Connor

3 x MLF sensors s/n 100059, 100060, 100061 Sensors appear to be MLF-16 mislabelled as MLF-19s 0140013 x 3 FOC

OILOJOS X NEW SIN'S SES,

Ready For quote

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33966	Oxygen Sensor	0110705	100059	Yes

Service Repair Sheet SRS67877

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Francis Loch

Forth Valley Royal Hospital

Medical Physics

Specialist Clinical Technologist

01324 566 956

00004880

francis.loch@nhs.scot

30/Jun/2021

Robert Connor

Viamed

Warranty

Notes 28/Jun/2021 Steve Hardaker 28/Jun/2021 Steve Hardaker 28/Jun/2021 Steve Hardaker

Returning 3x 0110705 MLF-19 s/n 100059, 100060 & 100061 that have the wrong connector and looks like the wrong sensor body: it has a 3-pin Molex (see attached). It would make more sense that this is actually a different sensor with the wrong label applied.

Please check our stock before replacing; the customer is happy if we have to send the replacements in sealed bags instead of cans.

Added issue 227149 to SN to report to manufacturer.

30/Jun/2021 Catherine Spence

Stock that we have has been checked and is correct

30/Jun/2021 Steve Hardaker

28/Jun/2021 Steve Hardaker

28/Jun/2021 Steve Hardaker

28/Jun/2021 Steve Hardaker

Returning 3x 0110705 MLF-19 s/n 100059, 100060 & 100061 that have the wrong connector and looks like the wrong sensor body: it has a 3-pin Molex (see attached). It would make more sense that this is actually a different sensor with the wrong label applied.

Please check our stock before replacing; the customer is happy if we have to send the replacements in sealed bags instead of cans.

Added issue 227149 to SN to report to manufacturer.

30/Jun/2021 Catherine Spence

Stock that we have has been checked and is correct

Francis has shipped the sensors back by TNT, ref 244536518.

30/Jun/2021 Robert Connor

3 x MLF sensors s/n 100059, 100060, 100061

Sensors appear to be MLF-16 mislabelled as MLF-19s

0140013 × 3 FCC

OIIO705 X New SIN'S SRS.

Ready For quote

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33966	Oxygen Sensor	0110705	100059	Yes