



Tofo Scuba

CID9216 Opera **TOFO** Type:
Tofo Scuba Praia do Tofo, , Inhambane, , Mozambique,
 Tel **+258 29 329030** [Log Call](#)
 Proforma

- [Account Home](#)
[Main Details](#)
[Account Memos](#)
[Sales History](#)
[Stock References](#)
[Customer Returns](#)
[Service Visits](#)
[Distributor Agreements](#)
- [Documents Files](#)

SRS67904

[Print Barcodes](#)
[Print A4 Sheet](#)
[Split Items into Different SRS Numbers](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Handle with care
 Add Items to Supplier Returns Box

[Add](#)

☐ Return for Credit / Return to Stock
 Unopened - will apply to all items on srs
☐ Clear From System - Force from System. - will apply to all items on srs

Add notes to SRS

[Add Notes](#)

Service Repair Sheet 67904				Notes						
Company / Hospital	Tofo Scuba			19/Jul/2021 Robert Connor						
Contact Name				19/Jul/2021 Robert Connor						
Department				1 x VN202 s/n 00770, and coiled cable s/n 0000826, no paperwork.						
Position				19/Jul/2021 Ryan Swaine						
Company Phone				Quote from customer: Its currently reading 8.8, but if i touch the metal "jack" at the top it goes up to 10						
Direct Phone				27/Jul/2021 Catherine Spence						
Opera Account				In engineers room						
Email	info@tofoscuba.com			LINKED ISSUE NOTES:						
Order Number				230727 :						
Viamed ORD Number				AutoGenerated Issue SRS67904 Appears to be Complete						
Date Received Into building	19 Jul 2021			30 Jul 2021 Catherine Spence						
Issues?	230727			vandagraph repair						

Items for Repair

SRN	Equipment	Stock Reference	Serialnumber Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN34008	Oxygen Analyser VN202	7910100	870797	00770	VN202mkII - Auto Switch Off	No	No	Complete - Repaired	No Reading	01:30

Currently Viewing ITEM SRN34008 Oxygen Analyser VN202 7910100 00770 VN202mkII - Auto Switch Off

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The VN202mkII has been repaired. The battery contacts, sensor input connector, internal wiring have been replaced. The jack lead was found to be open circuit and has been replaced.	Non added Yet	The VN202mkII has been repaired. The battery contacts, sensor input connector, internal wiring have been replaced. The jack lead was found to be open circuit and has been replaced.

SELECT * FROM Serialnumbers where (1=0 OR Invoicenumber='WSSRN34008')

.