



Warning No company id linked:

Enter CID Number

SRS67950

[Print Barcodes](#)

[Print A4 Sheet](#)

[Split Items into Different SRS Numbers](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Handle with care

Add Items to Supplier Returns Box

- ☐ Return for Credit / Return to Stock
 Unopened - will apply to all items on srs
☐ Clear From System - Force from System.
 - will apply to all items on srs

Add notes to SRS

Service Repair Sheet 67950		Notes
Company / Hospital	Power Factor Correction	13/Sep/2021 Gail Bell
Contact Name	Sean Burke	13/Sep/2021 Gail Bell
Department		13/Sep/2021 Gail Bell
Position		
Company Phone	07974572154	Bought a tek ox from SDS at an exhibition. Having trouble with the readings jumping all over the place, the sensor was bought from us 7.4.2021 so in warranty
Direct Phone		05/Oct/2021 Robert Connor
Opera Account		Received 1 x tekox s/n TX2498, in yellow case with blue tee, sensor and flow diverter.
Email	sean@powerfactorcorrection.co.uk	LINKED ISSUE NOTES:
Order Number		238533 :
Viamed ORD Number		AutoGenerated Issue SRS67950 Appears to be Complete
Date Received Into building	05 Oct 2021	
Type	Quote Before Repair	
Issues?	238533	

Items for Repair

...										
SRN	Equipment	Stock Reference	Serialnumber Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN34225	Vandagraph Tek Ox	7910211	1182979	TX2498	Oxygen Analyser Tek-Ox	No	No	Complete - Repaired	Erratic reading	00:00

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Tek-Ox analyser has been repaired free of charge. The calibration control pot has been replaced. No fault was found with the R-17VAN Oxygen sensor.	07/Oct/2021 Michael Green The Tek-Ox analyser has been tested. The unit has a fault with the calibration pot. Pressing the pot causes the reading to fluctuate. 12/Oct/2021 Michael Green The Tek-Ox analyser has been repaired free of charge. The calibration control pot has been replaced.	The Tek-Ox analyser has been repaired free of charge. The calibration control pot has been replaced. No fault was found with the R-17VAN Oxygen sensor.