Service Repair Sheet SRS67968

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

David Mauron

Company/ Hospital Name

Nufer Medical (USD A/C)

d.mauron@nufer-medical.ch

Department

Service Technician

Position Direct Phone

+4131 958 66 66

General Phone

0041 31 9586666

Opera Account

00007786

Email

Order Number

Date Received

12/Oct/2021 Robert Connor

Booked in By Main Company

Viamed

Type Return

**Bring To Attentention** 

Notes 29/Sep/2021 Ryan Swaine 29/Sep/2021 Ryan Swaine

0110073 Medical Oxygen Sensor R-22VA REF: 0110039 S/No: V100936 (2020-05). Has a smaller top so unable to connect to ATOM incubator.

12/Oct/2021 Robert Connor

Received 1 x R22VA s/n V100936

Ready For quote

CONSON 25-10-2021

Repair Complete Signed

SRN		Stock Ref	Serial Number	
SRN34229	Oxygen Sensor	0110039	V100936	Yes

and 0140013 ×1 & £0.00 SID, SRS, SRN

0110039 x 1. 8 60.00 NEW S/W, SRS, SLD

UPSX1 & E0.00.

Service Repair Sheet SRS67968 Date Promised to Return: 01 Jan 1970 -3600 Contact Name David Mauron Company/ Hospital Name Nufer Medical (USD A/C) Department Position Service Technician Direct Phone +4131 958 66 66 General Phone 0041 31 9586666 Opera Account 00007786 Email d.mauron@nufer-medical.ch Order Number Date Received 12/Oct/2021 Booked in By Robert Connor Main Company Viamed Type Return Warranty Notes 29/Sep/2021 Rvan Swaine 29/Sep/2021 Ryan Swaine 0110073 Medical Oxygen Sensor R-22VA REF: 0110039 S/No: V100936 (2020-05). Has a smaller top so unable to connect to ATOM incubator. 12/Oct/2021 Robert Connor Received 1 x R22VA s/n V100936 12/Oct/2021 Robert Connor Cell is in warranty for customer, but out of warranty with EnviteC. 18/Oct/2021 Catherine Spence SRS67968 SRN34229 S/N: V100936 sold as a matched pair (0110073) sold on RVM131920-1 on 06/08/2021

18/Oct/2021 Catherine Spence outer measurement should be 16.8mm the one sent back is 14mm

19/Oct/2021 Catherine Spence

spoken to steve nixon, measured top of senor and its smaller than it should be, to return to honeywell, replace faulty sensor to nufer under warranty need to match the output as its part of a pair

returned as the connector top is smaller than usual and will not connect into the ATOM incubator. Looked at stock that we have available and the returned sensor top does look a little smaller, think a randon cap has got into production as they have not returned any others not even the matched partner. Issue sent to SN #239053 and also skype message

20/Oct/2021 Catherine Spence

returned sensor out put is 11.035 will replace with serial number V101238 out put 11.039 checked through with derek

Ready For quote	
Repair Complete Signed	

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34229	Oxygen Sensor	0110039	V100936	Yes

031958666 NUFER MEDICAL AG MORGENSTRASSE 148 3018 BERN SWITZERLAND

SHIP TO:
MR. RYAN SWAINE
441535634542
VIAMED LIMITED
CROSS HILLS
15 STATION ROAD
KEIGHLEY BD207DT UNITED KINGDOM

SHP#: 8A15 58VN 4PD SHP WT: 0.5 KG SHP DWT: 0.5 KG DATE: 01 OCT 2021 DWT: 15,13,9



1 KG

**UPS SAVER** 

TRACKING #: 1Z 8A1 558 04 9861 2352



BILLING: F/C RECEIVER 9W9638 DESC: Oxygen Sensor

Rechnungsnummer: PF2101597 Auftragsnummer: SR\$67968 XOL 21-09-12

Shipper agrees to the US Terms found at www.ups.com and UPS service centers, for international air carriage, the Warsaw Convention as amended or Montreal Convention may personal military to the Convention on the Contract for the International Carriage of Goods By Road Exemples of State of Convention on the Contract for the International Carriage by road may Except as otherwise governor by international conventions or other loan data of Soods By Road Items limit UPS liability for darnage, loss or delay of this shipment. There are no stopping the shipment in any way it deems appropriate, where allowed by law shipper authorizes UPS shipper certifies that the commodities, technology or software were experted from the US in scrondance with the Export Administration Regulations. Diversion contrary to law is