Service Repair Sheet SRS68076

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Jody Willis

The Automation Partnership

Supply Quality Engineer

01763227200

01763227248

00009081

JODY.WILLIS@sartorius-stedim.com

03/Mar/2022

Robert Connor

Viamed

Warranty

Notes 16/Feb/2022 Steve Hardaker

16/Feb/2022 Steve Hardaker

â€∢Returning a Max-250(B) 0110432 for replacement under warranty. S/N: GC28999077.

Reported Fault:

See attached report showing the output from a bank of 24 sensors recorded by the TAP engineer. It is not in mV, its software generated, but clearly shows that this sensor (the bottom line and each graph) is behaving very differently to the other sensors.

George Jacovou chased this up but we haven t received it yet. Re-sent the SRS details for them to return it and asked for tracking number.

02/Mar/2022 Steve Hardaker Posted today, 2/3/22. Please can you let me know when we receive it, customer would like to be informed.

George says "A credit or replacement sensor is fine, whatever works best for you."

03/Mar/2022 Robert Connor

Received 1 x MAX-250 s/n GC28999077

Ready For quote

Repair Complete Signed

careen 7-3-22.

SRN	Equipment	Stock Ref	Serial Number	Warranty
ODNO 4756	Oxygen Sensor			

0140013 × 1 OID SIN, SRS, SRN

0110432 × 1 FOC New SIN, SRS, SRN

> FOC UPS

## SARTURIUS

The Automation Partnership (Cambridge) Ltd. - Royston

VIAMED LIMITED 15 STATION ROAD KEIGHLEY West Yorkshire BD20 7DT

## Complaint

First Sample no. / Date

1100069165 / 16.02.2022

Purchasing Document / Item

4561021520 / 00000

Material / description

S-0262 / SENSOR, OXYGEN, MAX-250B\_

Document / Version

Purchase Qty / Affected Qty

1.000 PC / 1.000

Vendor number / Reference number

999185

Ext. Delivery Note / Vendor Mat. No.

1

Inhouse contact / Telephone / Fax

Email

Dear sir or madam,

we analyzed the goods delivered by you and discovered the following:

Position 1

Faulty Sensor Low reading

Off-Gas O2 sensor reading is low (< 9 A-to-D counts). Re-tested multiple times with the same result.

Ref: R125P02-003

S/N: GC28999077

Machine 389 / Production Order 501274317

The Automation Partnership (Cambridge) Ltd. Royston Service Repair Sheet 68076

Contact Name

Jody Willis

Company/ Hospital Name

The Automation Partnership

Position

Supply Quality Engineer

Direct Phone General Phone 01763227200

Opera Account

01763227248

Email

00009081

Email

JODY.WILLIS@sartorius-stedim.com

Date Received Booked in By 03/Mar/2022 Robert Connor

Repair

Ref

S/N

**Equipment Type** 

**Under Warranty** 

SRN34756

0110432 GC28999077

Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0

0110432

Replaced under warranty with S/N GH82699054

.