Service Repair Sheet SRS68122

Contact Name

Company/ Hospital Name

Department Position

Direct Phone General Phone Opera Account

Email

Order Number
Date Received
Booked in By
Main Company
Type Return

Date Promised to Return: 01 Jan 1970 -3600

Brian Buick

Antrim Area Hospital

Estates Services Department Clinical Engineering Technician

02894424000 02894424000 00000126

Brian.Buick@northerntrust.hscni.net

06/Apr/2022 Robert Connor

Viamed Warranty

Notes 29/Mar/2022 Zoey Teal 29/Mar/2022 Zoey Teal Sending back a faulty pair of the R-22Vi sensors. Serial numbers V104537-38 06/Apr/2022 Robert Connor Received 2 x R22VI s/n V104537, V104538

Ready For quote

Repair Complete Signed


CGNOON 7-4-22.

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34937	Oxygen Sensor	0110072	V104537/V104538	Yes

0146013 × 1 2 60.

0110072 × 10 60 New SIN, 525, 5EN

UPS > 1 0 60



29 March 2022

Viamed returns # SRS 68122

Please find enclosed a matched pair of R-22 O2 cells (SN-v104537 & V104538).

The O2 cells were purchased in July 2021 and fitted in September 2021.

Could we have a replacement pair of R22 cells under warranty please?

Regards

Brian Buick

Brandwich

Clinical Engineering Technician

02894424576 (works HOP)

Service Repair Sheet 68122

Contact Name

Company/ Hospital Name

Department Position Direct Phone

General Phone Opera Account

Email

Date Received Booked in By Brian Buick

Antrim Area Hospital

Estates Services Department Clinical Engineering Technician

02894424000 02894424000

00000126

Brian.Buick@northerntrust.hscni.net

06/Apr/2022 Robert Connor

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34937 0110072

0110072 V104537/V1045380xygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1 0110072

The R-22Vi Oxygen sensors have been replaced under warranty with SN:V105587/V105588.