



**Calbee Group (UK)
Ltd.**

 CID15734 Opera CID15734 Type: **Vandagraph Retail**
Calbee Group (UK) Ltd. Duncombe Street, , Bradford, West Yorkshire,
BD8 9AJ,

Tel 01274 546405



Credit 30 Days after date of invoice

 Account Home

 Main Details

Account Memos

 Sales History

Stock References

Customer Returns

 Service Visits

Distributor Agreements

Documents
Files

 Linked Issues

Regulatory Agreements

SRS68180

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

Handle with care

Add Items to Supplier Returns Box



☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs

☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS



Add Notes

Service Repair Sheet 68180		Notes
Company / Hospital	Calbee Group (UK) Ltd.	25/May/2022 Ryan Swaine
Contact Name	Sue Davey	25/May/2022 Ryan Swaine 3x VN202 - To check over and quote for repair
Department		30/May/2022 Robert Connor Received 3 x VN202 in black hard carry cases s/n 00061, with sensor s/n 823243, and blue tee, s/n 01314, with yellow coiled cable, s/n 00034 with yellow cable. Cases all have broken clips.
Position	Technical Manager	10/Jun/2022 Catherine Spence in engers room, with ryan quoting customer
Company Phone	01274 546405	22/Jun/2022 Catherine Spence engineers room, ryan to do quote
Direct Phone	01274 546405	
Opera Account	CID15734	
Email	sued@calbeegroupuk.com	
Order Number		
Viamed ORD Number		
Date Received Into building	30 May 2022	
Type	Quote Before Repair	
Issues?		

Items for Repair

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN35067	Oxygen Analyser VN202	7900100	 502853	00061	Oxygen Analyser VN202 Mk2	No	No	Quote	No Reading	00:30
SRN35067 Engineer Notes: INTERNAL NOTES not for customer discussion 09/Jun/2022 Michael Green The Oxygen Analyser VN202 Mk2 has been tested. The unit powers up, but fails to read the Oxygen sensor. The sensor input socket and wiring loom need to be replaced.										
SRN35068	Oxygen Analyser VN202	7900100	 494193	00034	Oxygen Analyser VN202 Mk2	No	No	Quote	No Reading	00:30
SRN35068 Engineer Notes: INTERNAL NOTES not for customer discussion 09/Jun/2022 Michael Green The Oxygen Analyser VN202 Mk2 has been tested. The unit powers up, but fails to read the Oxygen sensor. The sensor input socket and wiring loom need to be replaced.										
SRN35069	Oxygen Analyser VN202	7900100	 1373613	01314	Oxygen Analyser VN202 Mk2	No	No	No Fault Found	No Fault Found	00:00
SRN35069 Engineer Notes: INTERNAL NOTES not for customer discussion 09/Jun/2022 Michael Green The Oxygen Analyser VN202 Mk2 has been tested. The unit powers up and reads the Oxygen sensor. No fault was found.										
SRN35070	Oxygen Sensor Vandagraph	R-17VAN	 486273	823243	OXYGEN SENSOR	No	No	Quote	No Output	00:00
SRN35070 Engineer Notes: INTERNAL NOTES not for customer discussion 09/Jun/2022 Michael Green The R-17VAN Oxygen sensor has been tested. The sensor has no output.										
SRN35079	Oxygen Sensor	0110157	 1349732	V100001	Oxygen sensor - R-17A-LVG	No	No	Quote	Low Output	00:00
SRN35079 Engineer Notes: INTERNAL NOTES not for customer discussion 09/Jun/2022 Michael Green The Oxygen sensor - R-17A-LVG has been tested. The output in air was 6.1mV. The sensor has expired. A R-17VAN will be quoted for as a replacement.										
SRN35079	Output mV					6.1				
SRN35080	Oxygen Sensor Vandagraph	0110217	 1597768	509959		No	No	No Fault Found	No Fault Found	00:00
SRN35080 Engineer Notes: INTERNAL NOTES not for customer discussion 09/Jun/2022 Michael Green The R-17VAN Oxygen sensor has been tested. The sensor is within specification, but is likely near the end of expected life span.										
SRN35081	Oxygen Sensor Vandagraph	0110217	 1597769	509960		No	No	Quote	New	00:00
SRN35081 Engineer Notes: INTERNAL NOTES not for customer discussion 09/Jun/2022 Michael Green The R-17VAN Oxygen sensor has been tested. The sensor has no output.										
SRN35082	Oxygen Monitor Cable	0131203	 459275	0000076	Oxygen Sensor Cable - Yellow	No	No	No Fault Found	No Fault Found	00:00
SRN35082 Engineer Notes: INTERNAL NOTES not for customer discussion 09/Jun/2022 Michael Green The Oxygen sensor cable has been tested. No fault was found.										
SRN35083	Accessory	7910300	 589992	PR01358A10		No	No	Quote	New	00:30
SRN35083 Engineer Notes: INTERNAL NOTES not for customer discussion 09/Jun/2022 Michael Green The pump box has been tested. The unit has sufficient draw. The internal tubing and sample line should be replaced.										
SRN35084	Accessory	7910300	1372139	PR02778A10		No	No	Quote	New	00:30
SRN35084 Engineer Notes: INTERNAL NOTES not for customer discussion 09/Jun/2022 Michael Green The pump box has been tested. The unit has sufficient draw. The internal tubing and sample line should be replaced.										

SRN35085	Accessory	7910300	 589993	PR01358A11		No	No	Quote	New	00:30
SRN35085 Engineer Notes: INTERNAL NOTES not for customer discussion 09/Jun/2022 Michael Green The pump box has been tested. The unit has sufficient draw. The internal tubing and sample line should be replaced.										

Currently Viewing ITEM SRN35067 Accessory 7910300 PR01358A11

[Create a Meeting Issue](#)

Items Requested for Repair					Item notes	Engineer Notes	Notes To Customer
Item	Qty	By	Date Requested	Status	Non Supplied	09/Jun/2022 Michael Green The pump box has been tested. The unit has sufficient draw. The internal tubing and sample line should be replaced.	Non added Yet
LABOUR	0.5	Michael Green	09/Jun/2022	Quote			
7920300	1	Michael Green	09/Jun/2022	Quote			
9711501	1	Michael Green	09/Jun/2022	Quote			

-