



Steve Nixon <steve.nixon.viamed@gmail.com>

Re: Exploded O2 cell

1 message

Steve Nixon <steve.nixon@vandagraphst.com>

28 November 2018 at 10:52

Reply-To: steve.nixon@vandagraphst.com

To: "Jan P. jj-ccr" <jp@jj-ccr.com>

Hi Jan

I have tried to phone both you and Dave to discuss further.

We have never seen such a situation before. How did this occur: during a dive, during testing?

What has been the dive history of this sensor.

There is a pressure equalization hole on the rear cap.

We need this sensor back for evaluation, can you please return it using returns number: **SRS66842**

Regards

Steve

On Wed, 28 Nov 2018 at 08:13, JJ-CCR <jp@jj-ccr.com> wrote:

Morning Steve,

Pleas have a look to the below Jos in the netherlands have had a sensor explosion, what can have happened here.

Kind regards

Jan Petersen**JJ-CCR ApS** · Dyrlevvej 11 · 4720 Presto · Denmark

Phone direct: +45 40108982

Email: jp@jj-ccr.comWeb: www.jj-ccr.com

----- Videresendt besked -----

Fra: DiveWise Techn Diving <technicaldiving@divewise.nl>

Dato: 27. november 2018 kl. 14.06.16 +01.00

Emne: Exploded O2 cell

Til: JJ <jp@jj-ccr.com>

Hi Jan

Wil bring another small present next week.

Found the surprise this morning preparing my unit for Tx diving later this week.

One of the cell has exploded , chemical reaction in the cell by the looks of it. Its one of 3 cells recently replaced in sept this year (see batch date aug 18 on pic #2)

Looking fw to next week Jan!

Grts

Jos

Divewise Technical Diving

www.divewise.nl

Steve

Steve Nixon
Director - Vandagraph Sensor Technologies Ltd.

Office: +44 (0)1535 634900
Mobile: +44 (0)7850 252267

4 attachments




image1.jpeg
73K



image2.jpeg
71K



image1.jpeg
73K



image2.jpeg
71K