



Steve Nixon <steve.nixon.viamed@gmail.com>

Fwd: Re: Exploded O2 cell

1 message

JJ-CCR <jp@jj-ccr.com>

28 November 2018 at 12:38

Reply-To: jp@jj-ccr.com

To: "steve.nixon@vandagraphst.com" <steve.nixon@vandagraphst.com>

Hi steve.

I asked the coustomar for feedback pleas see below in text.

Kind regards

Jan Petersen**JJ-CCR ApS** · Dyrlevvej 11 · 4720 Presto · Denmark

Phone direct: +45 40108982

Email: jp@jj-ccr.comWeb: www.jj-ccr.com

----- Videresendt besked -----

Fra: DiveWise Techn Diving <technicaldiving@divewise.nl>

Dato: 28. november 2018 kl. 13.37.00 +01.00

Emne: Re: Exploded O2 cell

Til: jp@jj-ccr.com

Sure Jan

I have added answers to the
Questions. Was not sure if you wanted me to respond directly to Steve. Feel free to send this response to Steve

Brgds

Jos
Divewise Technical Diving

www.divewise.nlOp 28 nov. 2018 om 12:57 heeft JJ-CCR <jp@jj-ccr.com> het volgende geschreven:

Hi Jos,

I have forwarded your mail about the exploded sensor to vandagraph they are asking a few questions can you pleas have a
look and see if you can answer them.

Kind regards

Jan Petersen**JJ-CCR ApS** · Dyrlevvej 11 · 4720 Presto · Denmark

Phone direct: +45 40108982

Email: jp@jj-ccr.com

Web: www.jj-ccr.com

----- Videresendtd besked -----

Fra: Steve Nixon <office@viamed.co.uk>

Dato: 28. november 2018 kl. 11.52.20 +01.00

Emne: Re: Exploded O2 cell

Til: Jan P. jj-ccr <jp@jj-ccr.com>

Hi Jan

I have tried to phone

We have never seen such a situation before. How did this occur: during a dive, during testing?

Answer owner: happened when cell was in storage place after a diving weekend. JJ head completely crean from moisture after drying the head as usual.

What has been the dive history of this sensor.

Batch from 08-2018 replaced (taken out of vacuum sealed bag) in sept 2018. Not done more than 15 dives with cell since installation. Logbook available. Last dive on 55 m with Tx15/45

There is a pressure equalization hole on the rear cap.

Did investigate rear hole and this one is completely clear see pict below.



We need this sensor back for evaluation, can you please return it using returns number: **SRS66842**

Regards

Steve

On Wed, 28 Nov 2018 at 08:13, JJ-CCR <jp@jj-ccr.com> wrote:

Morning Steve,

Pleas have a look to the below Jos in the netherlands have had a sensor explosion, what can have happened here.

Kind regards

Jan Petersen

JJ-CCR ApS · Dyrlevvej 11 · 4720 Presto · Denmark

Phone direct: +45 40108982

Email: jp@jj-ccr.com

Web: www.jj-ccr.com

----- Videresendt besked -----

Fra: DiveWise Techn Diving <technicaldiving@divewise.nl>

Dato: 27. november 2018 kl. 14.06.16 +01.00

Emne: Exploded O2 cell

Til: JJ <jp@jj-ccr.com>

Hi Jan

Wil bring another small present next week.

Found the surprise this morning preparing my unit for Tx diving later this week.

One of the cell has exploded , chemical reaction in the cell by the looks of it. Its one of 3 cells recently replaced in sept this year (see batch date aug 18 on pic #2)

Looking fw to next week Jan!

Grts

Jos

Divewise Technical Diving

www.divewise.nl

--

Steve

Steve Nixon

Director - Vandagraph Sensor Technologies Ltd.

Office: +44 (0)1535 634900

Mobile: +44 (0)7850 252267

<image1.jpeg>