

Agenda ID: 291

VIAMED Feedback - Product Feedback Negative

Issues in VIAMED Feedback - Product Feedback Negative

All	Expand	Issue	Created By	Created On	Currently With	Subject	
✖ Live	⬇	268776	Steve Hardaker	11/08/22	Steve Nixon	Sampling lines in high humidity - 4420922	
✔ Complete	⬇	261682	Steve Hardaker	30/05/22	Steve Nixon	TOF 3D battery covers	
✖ Live	⬇	256351	Steve Hardaker	05/04/22	Steve Nixon	VM-2160 SMARTsat not picking up on neonates	
✔ Complete	⬇	255021	Michael Green	24/03/22	Steve Nixon	TOF 3D - Battery door cracked	
✖ Live	⬇	254991	Steve Hardaker	24/03/22	Steve Nixon	Feedback from Pinderfields Hospital re TOF 3D simulator	
✔ Complete	⬇	254464	Steve Hardaker	18/03/22	Steve Nixon	Reluctance to trial the TOF 3D	
✔ Complete	⬇	253608	Steve Hardaker	09/03/22	Steve Nixon	Kettering Hospital feedback on TOF 3D	
✖ Live	⬇	252744	Steve Hardaker	01/03/22	General	MaxO2ME falling out of V-mount brackets	
✔ Complete	⬇	252208	Steve Hardaker	24/02/22	Steve Nixon	Further reports of R-22AVG failures	
✖ Live	⬇	249504	Steve Hardaker	28/01/22	Steve Nixon	400-AC temperature probes - cleaning and sterilising	
✔ Complete	⬇	246283	Ryan Swaine	23/12/21	Steve Nixon	EyeMax - Modern Technology Company	
✔ Complete	⬇	230523	Steve Hardaker	28/07/21	Steve Nixon	Feedback from a TOF 3D trial at Hull Royal and Castle Hill Hospital	
✔ Complete	⬇	230031	Catrin Hird	23/07/21	Steve Nixon	R-48V Feedback from Oxylink	
✔ Complete	⬇	227149	Steve Hardaker	28/06/21	Catherine Spence	Manufacturing error - MLF-19 sensors with incorrect connector	
✔ Complete	⬇	224476	Steve Nixon	02/06/21	Derek Lamb	Maxtec MAX02+AE units possible production issue	
✔ Complete	⬇	217880	Steve Nixon	29/03/21	Steve Hardaker	0110047 R-47V - Inspiration Healthcare	
✔ Complete	⬇	215040	Steve Hardaker	25/02/21	Steve Hardaker	Ceratherm 600-3 with missing circlip	
✔ Complete	⬇	211010	Steve Hardaker	15/01/21	Steve Nixon	Oxygen sensor bags not sealed	
✔ Complete	⬇	168239	Ryan Swaine	10/03/20	Steve Nixon	MAX-16 (0110416) - New Design/Manufacturer - Response Required	
✔ Complete	⬇	163257	Steve Hardaker	24/01/20	Derek Lamb	VM-2160 disposable sensors displaying a "Sensor defective" error	
✔ Complete	⬇	163256	Steve Hardaker	24/01/20	Steve Hardaker	VM-2160 disposable sensors displaying a "Sensor defective" error	
✔ Complete	⬇	159422	Steve Hardaker	27/11/19	Catherine Spence	Quality issues with resus mattresses	

Complete		145928	Steve Hardaker	24/05/19	Steve Nixon	VM-2500-S not powering on	
Complete		141783	Steve Hardaker	03/04/19	Steve Nixon	R-22AV customer moving to R-22AVG due to high failure rate	
Complete		139219	Steve Hardaker	27/02/19	Steve Nixon	Automotive customer moving from R-22AV to R-22AVG	
Complete		134228	Steve Hardaker	13/12/18	Steve Nixon	R-22AV failures - CARS automotive	
Complete		134203	Steve Hardaker	13/12/18	Steve Nixon	R-17A-LV high failure rate	
Complete		130177	Steve Hardaker	12/10/18	Steve Nixon	R-22AV failures - high output	
Complete		127022	Steve Hardaker	30/08/18	Steve Nixon	Maxtec FloCap pricing feedback	
Complete		124708	Ryan Swaine	25/07/18	Steve Nixon	Oridion compatible Versastream - 4420923 & 4420924	
Complete		124601	Steve Hardaker	24/07/18	Steve Nixon	Microstim knob failures	
Complete		124004	Ryan Swaine	13/07/18	Steve Nixon	Problems with size of R-17MED in Siare Morpheus	
Complete		123904	Ryan Swaine	12/07/18	Steve Nixon	Precision Blender - Wrong Fittings on O2 hose	
Complete		120509	Steve Hardaker	18/05/18	Steve Nixon	Out of box ISA module failure	
Complete		118153	Steve Hardaker	13/04/18	Michael Green	R43V label - not for clinical use	
Complete		117153	Steve Hardaker	29/03/18	Steve Hardaker	R-22A failures reading high - JHM Butt	
Complete		115518	Ryan Swaine	02/03/18	Steve Nixon	Atom Sensor - R-22VA - 0110039	
Complete		109412	Steve Hardaker	30/11/17	Steve Nixon	VM-2500 alarm volumes	
Complete		100588	Steve Hardaker	11/08/17	Steve Nixon	V1000 failures - needs a response	
Complete		100173	Steve Hardaker	07/08/17	Philip Crossley	Tom Thumb with stuck gauge	
Complete		96975	Katie Evans	19/06/17	Steve Nixon	VM2500-s Vet	
Complete		95149	Sophie Lines	22/05/17	Steve Hardaker	0310304 - Radiant Warmer on mobile floor stand	
Complete		93661	Steve Hardaker	28/04/17	Jonathan Connor	Blocked sampling lines - 4420718	
Complete		93251	Ryan Swaine	21/04/17	Steve Nixon	Sampling Line S Pricing	
Complete		92818	Ryan Swaine	13/04/17	Steve Nixon	VM-2160 Greek Translation Errors	
Complete		91947	Steve Hardaker	31/03/17	Derek Lamb	Sticking Tom Thumb gauges	
Complete		87976	Steve Hardaker	27/01/17	Steve Nixon	Temperature compensation errors reported on R-17MED	

Complete		87513	Steve Hardaker	20/01/17	Derek Lamb	Tom Thumb gauge sticking	
Complete		87162	Steve Hardaker	16/01/17	Jonathan Connor	R-22Vi matched pairs	
Complete		86460	Ryan Swaine	04/01/17	Steve Hardaker	Blue Diamond Neonatal Head Positioners	
Complete		86341	Steve Hardaker	03/01/17	Steve Nixon	Microstim knobs failing - possible quality issue	
Complete		84103	Ryan Swaine	23/11/16	Derek Lamb	4000 series disposables - Nellcor compatible	
Complete		84101	Ryan Swaine	23/11/16	Derek Lamb	Sampling Line S Poland	
Complete		82639	Steve Hardaker	01/11/16	Derek Lamb	Ceratherm elements cracking	
Complete		82562	Steve Hardaker	31/10/16	Jonathan Connor	Disposable hoods - quality issues reported by 2 customers	
Complete		82552	Katie Evans	31/10/16	Jonathan Connor	Microstim Leads 2520000	
Complete		82094	Steve Hardaker	21/10/16	Steve Nixon	VM-2500 not suitable for use with NIV, NIPPV, CPAP, BiPAP ventilation	
Complete		82084	Steve Hardaker	21/10/16	Steve Nixon	Maxtec O-rings degrading in anaesthetic applications	
Complete		80450	Steve Hardaker	03/10/16	Steve Nixon	Temperature probes lifespan	
Complete		76219	Steve Hardaker	04/08/16	Steve Nixon	R-22MEDV premature failures	
Complete		74422	Catrin Hird	06/07/16	Steve Nixon	Flocap Product Feedback	
Complete		73004	Steve Hardaker	15/06/16	Steve Nixon	VM-2500-S broken pins	
Complete		69935	Steve Hardaker	14/04/16	General	R-26MED issue when used in Whisperflow 2	
Complete		69330	Catrin Hird	01/04/16	Steve Nixon	Paul Martin - Maxtec FLOCAP feedback	
Complete		68964	Steve Hardaker	23/03/16	Steve Nixon	R-17A-LV sensors going to sleep in their bags	
Complete		68826	Steve Hardaker	17/03/16	Steve Nixon	Tom Thumbs - out of box failure (SRS65337)	
Complete		68793	Catrin Hird	17/03/16	Derek Lamb	2810045 2810046 ebay feedback alfiefrankie2009	
Complete		68404	Steve Hardaker	08/03/16	Michael Green	Investigation into 0014706 and 0014804	
Complete		68098	Ryan Swaine	01/03/16	Steve Nixon	Feedback - Flocap - Jamjoom - Saudi Arabia	
Complete		66287	Katie Evans	08/01/16	Steve Nixon	PP8716	
Complete		65887	Steve Hardaker	22/12/15	Steve Nixon	Microstim leads failing	
Complete		65795	Steve Hardaker	17/12/15	Steve Nixon	Microstim leads	

Complete	📄	64033	Steve Hardaker	26/10/15	Steve Hardaker	Bradford Royal, Tom Thumb not reaching a PIP above 32cm H2O	📄
Complete	📄	63933	Steve Hardaker	22/10/15	Steve Nixon	VM-2160 software problem, brightness	📄
Complete	📄	63675	Steve Hardaker	13/10/15	General	Eyemax2 effectiveness	📄
Complete	📄	63257	Keith Taylor	29/09/15	Steve Nixon	Lost VM2500 Sales	📄
Complete	📄	63231	Catrin Hird	28/09/15	Jonathan Connor	MD300W1 Software Issue - Messages from Customer	📄
Complete	📄	62998	Steve Nixon	17/09/15	Steve Nixon	4420613 feedback from Masimo	📄
Complete	📄	62366	Catrin Hird	03/09/15	Emily Hanson	Posey Cufflator: Discontinued!	📄
🔴 Live	📄	62017	Steve Hardaker	19/08/15	Michael Green	Ceratherm 600-3 test procedure	📄
Complete	📄	61968	Steve Hardaker	18/08/15	Steve Hardaker	Ceratherm 600-3 heat output test	📄
Complete	📄	60476	Keith Taylor	08/07/15	Catrin Hird	Trachi Ties	📄
Complete	📄	60121	Catrin Hird	30/06/15	Catrin Hird	Neomask Feedback	📄
Complete	📄	59855	Steve Hardaker	18/06/15	Derek Lamb	R22-MEDV matched pairs - tighter matching spec	📄
Complete	📄	59854	Steve Hardaker	18/06/15	Steve Nixon	More R22-MEDV mismatched sensor failures	📄
Complete	📄	59746	Ryan Swaine	15/06/15	Jonathan Connor	R-23V - 0110023 - New sensors Tarnished	📄
Complete	📄	59643	Steve Hardaker	09/06/15	Steve Nixon	VM-2500 power connector problems	📄
Complete	📄	59394	Steve Hardaker	01/06/15	Steve Nixon	VM-2500-S lost sale feedback	📄
Complete	📄	58511	Keith Taylor	29/04/15	Steve Hardaker	Butterfly complaint	📄
Complete	📄	57514	Keith Taylor	20/03/15	Steve Nixon	VersaStream	📄
Complete	📄	56200	Steve Hardaker	29/01/15	Steve Nixon	18mm OD flow sensor divertor for R-26MED as used on Stephan F120	📄
Complete	📄	56037	Keith Taylor	23/01/15	Catrin Hird	SpiroTrue flowsensors	📄
Complete	📄	55949	Sophie Lines	20/01/15	Ryan Swaine	VM201, 2103 & 2105	📄
Complete	📄	55687	Steve Hardaker	07/01/15	Steve Nixon	Huntleigh V1000 feedback	📄
Complete	📄	55276	Steve Hardaker	23/12/14	Derek Lamb	Incomplete SRS to tidy	📄
Complete	📄	55275	Steve Hardaker	23/12/14	Steve Nixon	R-22MEDV matched pair problems	📄
Complete	📄	54904	Keith Taylor	10/12/14	Catrin Hird	Market Research-Versastream	📄
		54763	Sophie	04/12/14	Ryan	Viamed VM-2160 Feedback from Morning Star	

Complete			Lines		Swaine	Medical Equipment	
Complete		53316	Steve Hardaker	10/10/14	Steve Nixon	18mm OD flow sensor availability	
Complete		52908	Derek Lamb	29/09/14	Steve Nixon	4310002 disinfecting instructions	
Complete		51562	Ryan Swaine	30/07/14	Steve Nixon	Microstim DB3 2510000	
Complete		51276	Steve Hardaker	24/07/14	Keith Taylor	2710520 - Butterfly positioner. Complete discontinuation	
Complete		50895	Steve Hardaker	01/07/14	Derek Lamb	4310002 flowsensor A(PC) failure	
Complete		50787	Steve Hardaker	25/06/14	Steve Nixon	Ohmeda disposable 4000 series - suggest immediate discontinuation	
Complete		50263	Steve Hardaker	13/05/14	Keith Taylor	0110021 connector aperture size/shape	
Complete		49501	Steve Hardaker	16/04/14	Steve Hardaker	Customer for Maxtec version of Covidien sensor for NPB840	
Complete		49320	Steve Hardaker	04/04/14	Steve Nixon	R43V failures - customer suspects a batch problem	
Complete		49220	Steve Hardaker	01/04/14	Steve Nixon	Microstim sale lost to a competitor product	
Complete		48775	Steve Hardaker	12/03/14	Steve Hardaker	Flowsensor A(PC) accuracy problems	
Complete		48213	Steve Hardaker	14/02/14	Steve Nixon	4310002 damaged by autoclaving	
Complete		45499	Ryan Swaine	18/09/13	Steve Hardaker	New Masimo Emma Capnograph	
Complete		45366	Steve Hardaker	10/09/13	Jonathan Connor	VM-2500-S failure during SOR trial	
Complete		45290	Keith Taylor	05/09/13	Steve Hardaker	Reduced Flowsensor sales	
Complete		45184	Steve Hardaker	30/08/13	Steve Nixon	Worcestershire Royal Hospital	
Complete		45182	Steve Hardaker	30/08/13	Steve Hardaker	Flowsensor A improvements	
Complete		44976	Steve Hardaker	16/08/13	Steve Nixon	MAX-16 failures - test results	
Complete		44399	Steve Hardaker	24/07/13	Steve Hardaker	Beanbag leak test procedure	
Complete		44226	Steve Hardaker	11/07/13	Derek Lamb	Resuscitation Cabinet - response to negative feedback	
Complete		44216	Keith Taylor	11/07/13	Steve Hardaker	Resuscitation Cabinet Demo	
Complete		43690	Keith Taylor	28/06/13	Steve Nixon	R-43V sensor failures	
Complete		43526	Steve Hardaker	18/06/13	Steve Nixon	AX300 / MX300 cables	
Complete		43106	Keith Taylor	03/06/13	Steve Nixon	Butterfly problems	

Complete		43065	Keith Taylor	31/05/13	Steve Hardaker	Whipps Cross Butterflies	
Complete		42820	Steve Hardaker	14/05/13	Steve Nixon	0110071 - R-22MEDV matched pairs	
Complete		42515	Steve Nixon	22/04/13	Steve Nixon	R-24MED quality issues - bent connector pins	
Complete		40398	Steve Hardaker	03/12/12	Derek Lamb	Tom Thumb QA sheet missing?	
Complete		40275	Keith Taylor	27/11/12	Steve Nixon	VM2500 AC/DC adaptor	
Complete		40065	Steve Hardaker	20/11/12	Steve Nixon	Butterfly Feedback	
Complete		39732	Steve Hardaker	26/10/12	Jonathan Connor	"Flash error" on VM-2500	
Complete		39731	Steve Hardaker	26/10/12	Steve Nixon	"Flash error" on VM-2500	
Complete		39609	Steve Hardaker	17/10/12	Steve Nixon	Problem with R-42V replacement sensor for Stephan	
Complete		38807	Steve Hardaker	11/09/12	Steve Nixon	Butterfly positioner marked	
Complete		38315	Steve Hardaker	22/08/12	Steve Hardaker	Sample flowsensor to send with labels	
Complete		38301	Steve Hardaker	22/08/12	Derek Lamb	Flowsensor A lifespan	
Complete		38188	Keith Taylor	14/08/12	Steve Nixon	TECcare leaflet feedback	
Complete		37946	Catrin Hird	02/08/12	Catrin Hird	TECcare Competitor	
Complete		37528	Steve Hardaker	04/07/12	Steve Nixon	VM-2500-S capnogram recording	
Complete		36978	Catrin Hird	08/06/12	Steve Nixon	Microstim DB3 from Terry Corin in New Zealand	
Complete		36519	Ryan Swaine	14/05/12	Steve Nixon	VM-2500 Nomo Adapter	
Complete		35642	Steve Hardaker	10/04/12	Steve Nixon	Feedback re VM-2500-MG multi-gas	
Complete		35547	Steve Hardaker	02/04/12	Steve Nixon	VM-2500-S - ET tube adapters	
Complete		34730	Steve Hardaker	01/03/12	Jonathan Connor	SRS62876 can now be resolved.	
Complete		34427	Steve Hardaker	20/02/12	Jonathan Connor	R-26MED thread issue	
Complete		33348	Steve Hardaker	04/01/12	Steve Nixon	4000 series disposable sensor packaging	
Complete		33206	Steve Hardaker	22/12/11	Catherine Spence	Urgent QA issue - Bag sealing problem, flowsensor H	
Complete		32995	Catrin Hird	13/12/11	Steve Nixon	Capnograph Pricing	
Complete		32351	Steve Hardaker	18/11/11	Steve Nixon	Flowsensor A pin spacings	

Complete		31450	Steve Hardaker	14/10/11	Steve Nixon	R-22AV possibly too high for V-Tech	
Complete		30654	Steve Hardaker	06/09/11	Jonathan Connor	Replacement AX/MX300 cable to send FOC	
Complete		30461	Steve Hardaker	22/08/11	Jonathan Connor	Microstim leads for Barnsley	
Complete		30451	Steve Hardaker	22/08/11	Steve Nixon	Flowsensor A and humidity	
Complete		30281	Steve Hardaker	09/08/11	Jonathan Connor	VM-2500-M coming back for repair	
Complete		29880	Steve Hardaker	26/07/11	Steve Nixon	More nomo feedback	
Complete		29845	Steve Hardaker	26/07/11	Catrin Hird	Operators manual for VM-2500	
Complete		28679	Steve Hardaker	23/05/11	Steve Hardaker	VM-2500 data preservation	
Complete		28555	Steve Hardaker	17/05/11	Steve Nixon	Further feedback regarding NOMO adapters	
Complete		28506	Steve Hardaker	13/05/11	Steve Nixon	Hamilton flowsensor feedback	
Complete		28488	Keith Taylor	11/05/11	Steve Hardaker	Flowsensor - H	
Complete		28486	Keith Taylor	11/05/11	Steve Hardaker	FS - H	
Complete		28077	Steve Hardaker	01/04/11	Steve Hardaker	4000 series Philips sensors rejected	
Complete		28018	Steve Hardaker	31/03/11	Derek Lamb	Microstim leads quality issue	
Complete		27835	Keith Taylor	18/03/11	Steve Hardaker	Product complaint-R24	
Complete		27302	Steve Hardaker	15/02/11	Steve Nixon	R43V - Old manufactured dates	
Complete		27051	Steve Hardaker	28/01/11	Steve Nixon	NOMO adapter feedback from an ITU	
Complete		26763	Steve Hardaker	11/01/11	General	VM-2105 not performing with poorly perfused or cold patients	
Complete		26722	Steve Hardaker	07/01/11	Steve Nixon	Oxygen hoods	
Complete		26053	Catrin Hird	25/11/10	Steve Nixon	Capnograph Spec	
Complete		26041	Jonathan Connor	25/11/10	Steve Nixon	VM2105/6	
Complete		26006	Jonathan Connor	22/11/10	Steve Nixon	0110026 Case Fault	
Complete		25977	Jonathan Connor	18/11/10	Steve Nixon	0110026	
Complete		25975	Jonathan Connor	18/11/10	Steve Nixon	0110026 R-26	
Complete		25947	Jonathan Connor	17/11/10	Jonathan Connor	0014608 and 0014708 on Tuffsat	

Complete		25021	Steve Hardaker	10/09/10	Steve Nixon	VM-2500-M failure	
Complete		25014	Steve Hardaker	09/09/10	Ryan Swaine	VM-2500-S doesn't work on batteries.	
Complete		25013	Steve Hardaker	09/09/10	Steve Nixon	VM-2500-S doesn't work on batteries.	
Complete		24522	Steve Hardaker	06/08/10	Jonathan Connor	4000 series failure	
Complete		24475	Steve Hardaker	04/08/10	Steve Nixon	Temperature probe failures	
Complete		23169	Steve Hardaker	22/03/10	Steve Hardaker	Feedback re flowsensor A	
Complete		22969	Derek Lamb	04/03/10	Steve Nixon	Viamed Products Lanyard	
Complete		22968	Derek Lamb	04/03/10	Steve Nixon	VM-2500 Operating Temperature	
Complete		22962	Sarah Wilford	04/03/10	Steve Nixon	VM-2500 - Norvic Ambulance Feedback	
Complete		22541	Steve Hardaker	26/01/10	Derek Lamb	MAX-43 failures under warranty - lost customer	
Complete		22526	Steve Hardaker	22/01/10	General	Disposable oxygen hoods	
Complete		22157	Sarah Wilford	22/12/09	Steve Nixon	Finger Oximeters on Paediatrics	
Complete		22051	Steve Hardaker	09/12/09	Steve Nixon	Hamilton flowsensor failure	
Complete		22049	Steve Hardaker	09/12/09	General	R-22MED thread issue	
Complete		21725	Jonathan Connor	17/11/09	General	R-22 Thread Issue 0110022	
Complete		20792	Sarah Wilford	11/09/09	Steve Nixon	VM-2160 & rechargeable battery	
Complete		20366	Steve Hardaker	25/08/09	Steve Nixon	Teledyne oxygen monitor resolution	
Complete		20100	Steve Hardaker	29/07/09	Steve Nixon	Potential thread problem with R22MEDs,	
Complete		20095	Steve Hardaker	29/07/09	Steve Nixon	VM-2105 failure during trial with Scottish Ambulance	
Complete		19778	Steve Hardaker	03/07/09	Steve Nixon	NeoPEEP - over-tight PEEP valves	
Complete		19678	Steve Hardaker	18/06/09	Steve Hardaker	R22 technical problem	
Complete		19458	Steve Hardaker	28/05/09	Steve Nixon	0014701 incompatibility problems	
Complete		19441	Sarah Wilford	26/05/09	Steve Nixon	VM-2160 in Restraint & Control Situations	
Complete		19139	Steve Hardaker	13/05/09	Steve Nixon	V1000 gel pad	
Complete		19074	Sarah Wilford	08/05/09	Sarah Wilford	Straight sensor cables to be replaced	

Complete		18993	Steve Hardaker	24/04/09	Steve Nixon	MX300 cable	
Complete		18992	Ryan Swaine	24/04/09	General	Heat Shields	
Complete		18988	Steve Hardaker	24/04/09	Steve Nixon	MX300 cable failure - Ipswich	
Complete		18934	Steve Hardaker	20/04/09	Steve Nixon	Feedback on VM-2101 from paramedic	
Complete		18933	Ryan Swaine	20/04/09	Steve Nixon	VM-2105	
Complete		18900	Sarah Wilford	17/04/09	Steve Nixon	Disposable Laryngoscopes	
Complete		18654	Steve Hardaker	31/03/09	Steve Nixon	More AX/MX cable failures	
Complete		18648	Sarah Wilford	30/03/09	Steve Nixon	VM-2105 Orange	
Complete		18601	Ryan Swaine	25/03/09	General	2510000 - Microstim DB3	
Complete		18472	Sarah Wilford	13/03/09	Steve Nixon	VM-2105 Feedback	
Complete		18187	Steve Hardaker	03/03/09	Steve Nixon	Blue diamond pads	
Complete		17922	Steve Hardaker	13/02/09	General	VM-2160 feedback from Yorkshire Ambulance	
Complete		17914	Steve Hardaker	11/02/09	General	4000 series feedback	
Complete		17363	Steve Hardaker	05/01/09	Sarah Wilford	Nova disposable hoods - instructions to update	
Complete		17003	Steve Hardaker	24/11/08	Steve Nixon	Eyemax feedback	
Live		16976	Keith Taylor	16/11/08		Eyemax	
Live		16931	Lisa Leggoe	06/11/08		Carry Case for VM2101 - Black	
Complete		16783	Steve Hardaker	24/10/08	Derek Lamb	AX/MX300 cable problem	
Complete		16592	Ryan Swaine	09/10/08	Steve Nixon	Wrap Sensors	
Complete		15613	Sarah Wilford	11/08/08	Steve Nixon	Autoclavable temperature probes	
Complete		15262	Keith Taylor	04/07/08	Steve Nixon	MAX-43	
Complete		14937	Steve Hardaker	13/06/08	Steve Nixon	2710250 heel protector	
Complete		14869	Steve Hardaker	09/06/08	General	VM2160 customer comment re. pricing	
Complete		14726	Sarah Wilford	27/05/08	General	NeoPEEP	
Complete		14041	Keith Taylor	18/03/08	Steve Nixon	Microstim S/No H0000301	
		13877	Ryan	05/03/08	General	Tom Thumb - Oriola - Finland	

Complete			Swaine				
 Complete		10293	Steve Hardaker	22/06/07	Steve Hardaker	R-45V for Viasys Avea	
 Live		7109	Steve Hardaker	08/11/06			