

Sales order 352188 - 10 x R125P01-007 missing from the shipment

1 message

Steve Nixon <steve.nixon@viamed.co.uk>
To: MXT-Maxtec Customer Service <customerservice@maxtec.com>
Bcc: Main Account <viamedinbox@gmail.com>

4 June 2025 at

Hi

We have received the following, but 10 of the R125P01-007 MAX-250 sensors are missing (serial numbers LD30499051 to LD30499060)

We have received 40 sensors instead of 50. Can you please resolve this.

SHIPMENT CONFIRMATION		
Sales Order: 352188 Customer PO#: PVM4461 Date Shipped: 6/2/2025		

SOLD TO		SHIP TO	BILL TO		
M5755		M5755	M5755		
VIAMED		VIAMED	VIAMED		
15 STATION RD		15 STATION RD	15 STATION RD		
CROSS HILLS, KEIGHLEY		CROSS HILLS, KEIGHLEY	CROSS HILLS, KEIGHLEY		
WEST YORKSHIRE, BD20 7DT		WEST YORKSHIRE, BD20 7DT	WEST YORKSHIRE, BD20 7DT		
GB		GB	GB		
<u>LN</u>	<u>Part ID</u>	<u>Description</u>	<u>Shipped</u>	<u>Bal Due</u>	<u>Ship Via</u>
1	R116P82-001	SENSOR OXYGEN, MAX-14 KORR CONNECTIONS	15	0	UPS Express Save
1	R116P82-001	SENSOR OXYGEN, MAX-14 KORR CONNECTIONS	5	0	UPS Express Save
2	R125P01-007	SENSOR,MAX-250 INTERNAL MED. WITH O-RING	50	0	UPS Express Save
3	R125P02-011	SENSOR, MAX-250+ INTERNAL MEDICAL	20	0	UPS Express Save
4	R125P11-001	SENSOR, MAX-250K VIASYS DC CONNET MED.	20	0	UPS Express Save
5	R140P02	SENSOR, MAX-550E EXTERNAL MEDICAL	20	0	UPS Express Save
999			0		WWE
					1Z8412980450253355

Steve

Steve Nixon
Director - Viamed Ltd.

Office: +44 (0)1535 634542
Mobile: +44 (0)7850 252267

GDPR / Privacy Policy available at www.viamed.co.uk/policy