

Steve Nixon <steve.nixon@viamed.co.uk>
to Vasu, bcc: steve.nixon

22:23 (10 hours ago)

Thanks Vasu, I will add the reply to our ISO files. Hopefully the issue is resolved.

If the issue lies at the ATS, would other sensors be affected?

Regards

 **Vasu P Narasimhan** via viamed.co.uk
to Steve

23:25 (9 hours ago)

Steve:

Other sensors are not affected, Steve. R22MED sensors are constructed differently at the board end, and are far easier to install in the ATS. Apparently, only R24 and R36 series sensors display the issue.

Best,

Vasu

From: steve.nixon.viamed@googlemail.com [mailto:steve.nixon.viamed@googlemail.com] **On Behalf Of** Steve Nixon
Sent: Tuesday, May 14, 2013 2:23 PM
To: Vasu P Narasimhan
Subject: RE: R-24MED quality issues

 **Steve Nixon** <steve.nixon@viamed.co.uk>
to Vasu

07:19 (1 hour ago)

That's good news thanks.