



Derek Lamb <liquidgands@gmail.com>

CE 565618

1 message

Derek Lamb <derek@lamb.uk.net>
To: Ben Wall <Ben.Wall@bsigroup.com>

9 August 2013 11:00

Dear Ben,

as part of the MHRA Ref: 2013/005/020/401/001, it appears my IFU of the Flow Sensor A in my technical file was incorrect,

The IFU supplied with the product, and the IFU supplied to customers on request are the correct versions,

How ever the version in my technical file was not.

as such I have opened a Non conformance report id#44815,

as part of the yearly review I will have emailed you the older versions of the IFU,

please find attached the current versions of the IFU of both ours and the original OEM's

Regards

Derek Lamb
Viamed Ltd.

2 attachments

 **4310001 Instructions for Use rev 1.4.pdf**
376K

 **3.5.1 Bedienungsanleitung-Rev1.4-05-2013-1030132006-SpiroTrueA.pdf**
75K