

10/03/2014

Here is one of the suspected faulty flow sensors.  
On a Drager XL it was reading VT insp 500 VT exp 590. The misreading was not seen when using a Drager flow sensor.

We have has a number of problems in the last few weeks with this same type of issue on several different vents. I am concerned that this is fault may be related to the new autoclavable sensors.

I haven't got time to look for more faulty sensors at the moment.

In the meantime we have ordered Drager sensors and as soon as they come we will be removing your product from use until I hear from you.

If you find a fault or we do then this will need reporting to all customers.

Martin Boichat

Royal Brompton Hospital