

Leaflet	Catalogue	Web site	Opera ref	Precision ref.	Oxygen Monitor	
Y	Y	To add	5610000	PM5900	PM5900 Oxygen Monitor	
Y	Y	To add	5620001	504877	Oxygen Sensor	Can use R-17Vi 0110019 instead.
Y	Y	To add	5620002	504937	Oxygen Sensor Cable	Could also use: 0131150, 0131201, 0313202
Y	Y	To add	5620003	505010	PM5900 V Mount Bracket	
Y	Y	To add	5620004	505120	PM5900 V Mount Bracket Screw	
Y		To add	5620005	505189	Wall Mount & Screws	Separate parts are: 5630003 & 5630004
Y		To add	5620006	505013	Vertical Pole Mount	
Y		To add	5620007	505014	Horizontal Pole Mount	
		To add	5620008	506451	Rail Mount, Horizontal	
			5620011	505126	T Piece	Use standard 0120100 instead
			5620012	505344	Flow Diverter	Use standard 0120099 instead
			5630001	504909	Battery Cover for PM5900	Spare part
			5630002	505122-4	Rubber Feet (qty 4) for PM5900	Spare part
			5630003	505012	Wall Mount	
			5630004	505712	Wall Mount Screws (2)	
			5690000	505127	PM5900 Oxygen Monitor User Manual	
				507270	Rail Mount, Horizontal	

Can also use Viamed mounting clamps instead: 0121180, 0121181, 0121182, 0121184