
A37016-T1 Teledyne Oxygen sensor T-1 - electrolyte leakage issue

1 message

Steve Nixon <steve.nixon@viamed.co.uk>

29 July 2026 at 13:03

To: IND_Repairs <ind_Repairs@teledyne.com>

Cc: "Ni, Wen Z" <Wen.Ni@teledyne.com>, Christina Reinoso - Teledyne <Christina.Reinoso@teledyne.com>

Bcc: Main Account <viamedinbox@gmail.com>

Hi

We are investigating leakage failures affecting stock reference **A37016-T1 Teledyne Oxygen sensor T-1**.

To date, 20 of 118 B6 date coded sensors have failed leakage testing. Five of these had originally passed incoming QA, but failed when rechecked. One of the two E6 sensors received has also now failed.

Previous returns:

Box 1072 — 11 B6 sensors

RMA: 0062919

Shipped: 18 March 2026

Tracking: 1Z9W96380441836447

Box 1090 — 4 B6 sensors

RMA: 0063547

Shipped: 28 July 2026

Tracking: 1Z9W96380441259599

All remaining B6 and E6 stock has been quarantined pending your response.

Please confirm urgently:

- 1) How the six newly failed (during QA testing) sensors should be returned;
- 2) Whether currently passing B6 and E6 sensors are safe to release;
- 3) Your root-cause investigation and corrective action;
- 4) Your advice regarding the B6 sensors already supplied.

--

Steve

Steve Nixon

Director - Viamed Ltd.

Office: +44 (0)1535 634542

Mobile: +44 (0)7850 252267

GDPR / Privacy Policy available at www.viamed.co.uk/policy

.