

Service Repair Sheet SRS68317

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Ted Gibbs

Southern Calibration Laboratories

01489790296

01489790296

CID22311

tedg@southcal.co.uk

SCL22/1230/5015

02/Nov/2022

Robert Connor

Viamed

Repair

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 01/Nov/2022 Kate Griffiths

01/Nov/2022 Kate Griffiths

Would like to send in V1000s for service and calibration - S/No 26946

S/No 26947. I am unable to locate these serial numbers in intrastats.

02/Nov/2022 Robert Connor

Received 2 x V1000, s/n PR0490A30, with grey silicone cover, blue fabric case, and 4 x AA battery, s/n PR0545A14, with grey silicone cover, blue fabric case, and 4 x AA battery.

02/Nov/2022 Robert Connor

Purchase order included for 102.00 GBP, 2 x 45 GBP + 12 GBP carriage.

Ready For quote

Repair Complete Signed

CGreen 3-11-22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35515	Foetal Simulator	1410000	PR0490A30	22
SRN35516	Foetal Simulator	1410000	PR0545A14	

1480000 x 2 @ £45 each

SIN, SRS, SRN

1430309 x 2 @ FOC

SRS, SRN

UPS x 1 @ £12

Service Repair Sheet 68317

Contact Name	Ted Gibbs
Company/ Hospital Name	Southern Calibration Laboratories
Direct Phone	01489790296
General Phone	01489790296
Opera Account	CID22311
Email	tedg@southcal.co.uk
Order Number	SCL22/1230/5015
Date Received	02/Nov/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN35515	1410000	PR0490A30	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309

V1000 has had transducer interface cushion replaced and calibration has been checked

Repair	Ref	S/N	Equipment Type	
SRN35516	1410000	PR0545A14	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309

V1000 has had transducer interface cushion replaced and calibration has been checked

Southern Calibration Laboratories Limited
Unit 7, Solent Industrial Estate
Hedge End
Southampton
SO30 2FX
TEL: 01489 790296
www.southcal.co.uk
tedg@southcal.co.uk



Purchase Order No. :- SCL22/1230/5015
RMA#SRS68317

To:- Viamed Ltd, Repairs Team, 15 Station Road, Cross Hills, Keighley, West Yorkshire, BD20 7DT	Shipment Via (Out) DPD
	Shipment Via(In) Viamed Ltd
	Customer Code/Job Number 3152/22101393 3152/22101394

Please supply the following goods at the price shown	
Please calibrate the following to Relevant National Standard and supply Certificate of Calibration, calibration label, integrity seal(s), a copy of calibration results(before & after adjustment – if applicable)	✓
Please repair the following and provide repair report (see reported fault(s) detailed below)	
Please investigate only and provide an estimate to repair only / repair & calibrate	

Quantity	Description	Price (£)
1	Viamed V1000 Foetal Heart Simulator S/No 26947 Plant No EME11764 C/w Case + Holster	45.00
1	Viamed V1000 Foetal Heart Simulator S/No 26946 Plant No EME11765 C/w Case + Holster	45.00
	Please calibrate as per your quote to Ted G	
	Carriage	12.00
	Total Order Value	102.00

Approved Supplier :- Yes		
Do not exceed purchase order value until written / fax / e-mail authority is received		
Confirmation of Purchase Order is required in writing or via fax / e-mail		
Purchase order place by :-		
Name Ted Gibbs	Signature	Date 01/11/2022
Authorised by:-		
Name Mike Hodge	Signature	Date 01/11/2022

SCL407/4

