

Service Repair Sheet SRS68358

Contact Name

Aneta Szubarga

Company/ Hospital Name

Euromed Medical Solution

Department

Position

Direct Phone

0048618439059

General Phone

504 078 773

Opera Account

00006582

Email

a.szubarga@euromed.net.pl

Order Number

Date Received

04/Jan/2023

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Bring To Attention

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☒

Signed: RS

Date: 4/1/23

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 04/Jan/2023 Robert Connor

04/Jan/2023 Robert Connor

Received 1 x V1000 s/n PR02968A11, with 4 x AA battery and hard plastic carry case.

No paperwork included, need to query customer on what they want doing.

Ready For quote

CGREEN 4-1-23

Repair Complete Signed

CGREEN 17-1-23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35595	Foetal Simulator	1410000	PR02968A11	<u>✓</u>

€
Dist

1480000 x 1 @ € 44.20

S/N, SRS, SRN

1430309 x 1 FOC

SRS, SRN



UPS x 1 @ 0.60kg 32x24x12cm



Catherine Spence 27 Issues 16 Unread 16 ISO Tasks | H/W: DL JG Future

Active Users 17.00 °C

Search



Select Currency

Pounds| Euros| Usd

Repair SRS68358 Values in Euros @ €1.16520: **€1.00**

SRN35595	Foetal Simulator	1410000			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		1480000	1	€52.43	€52.43
		1430309	1	€17.48	€17.48
				Parts Cost	€69.91

44.20€
FOC

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent

Service Repair Sheet 68358

Contact Name

Aneta Szubarga

Company/ Hospital Name

Euromed Medical Solution

Direct Phone

0048618439059

General Phone

504 078 773

Opera Account

00006582

Email

a.szubarga@euromed.net.pl

Order Number

paid proforma

Date Received

04/Jan/2023

Booked in By

Robert Connor

Repair	Ref	S/N	Equipment Type
SRN35595	1410000	PR02968A11	Foetal Simulator

Complete - Repaired
Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000

Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked
