

CID17146 Opera CID17146 Type:Vandagraph Retail

Christopher Howells 13 Castle Way, , Feltham, Middlesex, TW13 7NW, UK

Tel GBP Retail Price List Vandagraph (0010)

Add Issue

Proforma Credit Limit 0.00GBP

Account Home

Main Details

Account Memos

Sales History

Stock References

Cust./Supp. Returns

Service Visits

Distributor Agreements

Documents Files

Linked Issues

Regulatory Agreements

Log Call

SRS68356

SRS Created : 28 Dec 2022

Created By Ryan Swaine

Add Watch

[Print Barcodes](#)

[Print A4 Sheet](#)

[Split Items into Different SRS Numbers](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description

Choose a file to upload:

Choose file

 No file chosen

Next

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock

Unopened - will apply to all items on srs

☐ Clear From System - Force from System.

- will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68356																				
Company / Hospital	Christopher Howells																			
Contact Name	Christopher Howells																			
Department																				
Position																				
Company Phone																				
Direct Phone																				
Opera Account	CID17146																			
Email	howellschris@hotmail.co.uk																			
Order Number																				
Viamed ORD Number																				
Date Received Into building	04 Jan 2023																			
Issues?																				
Notes																				
28/Dec/2022 Ryan Swaine																				
28/Dec/2022 Ryan Swaine																				
R-22AT sensor, reading very slow on high mixtures.																				
Please give to MG to test, evaluate and inform RS of results.																				
04/Jan/2023 Robert Connor																				
Received 1 x R22AT s/n 101589, with thread adapter																				
17/Jan/2023 Catherine Spence																				
engineers room																				
Items for Repair																				
...																				
SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)										
SRN35583	Oxygen Sensor	0110238	1730247	101589	Oxygen sensor R-22AT	No	No	Unfinished		00:00										

https://www.vmsecure.me.uk/intranet/databases/repairs/viewrepair2.php?zz=1&A=&vui=13&user=Ryan Swaine&idp=raxYXanx9ACow&mph=&se... 1/2

SRN35583 Engineer Notes: **INTERNAL NOTES not for customer discussion**

20/Jan/2023 Michael Green

The R-22AT Oxygen sensor has been tested several times over the last week. The sensor has behaved as expected. The response time when swapping from air to Oxygen was typical for this sensor type. No fault was found.

Currently Viewing ITEM SRN35583 Oxygen Sensor 0110238 101589 Oxygen sensor R-22AT

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	20/Jan/2023 Michael Green The R-22AT Oxygen sensor has been tested several times over the last week. The sensor has behaved as expected. The response time when swapping from air to Oxygen was typical for this sensor type. No fault was found.	Non added Yet

-