

Invoice Correction 5262467024

Invoice Correction Date: 18.01.2023

Honeywell Healthcare Solutions GmbH

Alter Holzhafen 18

Purchase Order No: RTS3100897

23966 Wismar

Germany

Bill to: 1797448 Vandagraph Sensor Technologies Ltd. 15 Station Road Cross Hills, West Yorkshire KEIGHLEY BD20 7DT United Kingdom	Sold to: 1797448 Vandagraph Sensor Technologies Ltd. 15 Station Road Cross Hills, West Yorkshire KEIGHLEY BD20 7DT United Kingdom
--	--

Order Information: Credit Memo Request: 64010548 Sales Office: 2170 DE SPS Wismar Incoterms: FCA Origin Payment Terms: Net 30 Days After Invoice Date	Ship to: 1797448 Vandagraph Sensor Technologies Ltd. 15 Station Road Cross Hills, West Yorkshire KEIGHLEY BD20 7DT United Kingdom
--	--

EM NO.	Material No.	QTY	UOM	UNIT PRICE	EXT. PRICE	VAT %
00010	E1001721 Oxygen Sensor OOD103-2V Customer Part Nbr: 8010004	2	EA	31,14	-62,28	0%

credit note for SN: 140065; 141052

Totals

Total Before VAT	-62,28 EUR
VAT-Total	0,00 EUR
Total Amount	-62,28 EUR

Tax Information

Tax Exempt Reason:	Tax free export - Goods
Fulfilment Date:	18.01.2023

Integrity and Compliance at Honeywell

Honeywell places the highest value on the integrity of its business operations. We expect our employees and business partners to comply with our Code of Business Conduct and all applicable laws and regulations. If you become aware of illegal or improper conduct by a Honeywell employee please contact your Honeywell relationship manager. You can also report misconduct directly to us either via e-mail to our Integrity and Compliance Office at access.integrity.helpline@honeywell.com or via our access helpline accessible worldwide at 800-237-5982.

Invoice #:			
Bank Details: No Payment Due		Account Name:	
Account No:	Bank Key:	Swift Code:	
AN:		Payment method:	
Registered No:	Schwerin HRB 1838	VAT Reg No:	DE137437213
Federal ID #:			
Registered Address: Honeywell Healthcare Solutions GmbH, Alter Holzhafen 18, Wismar, 23966, Germany			
Credit Analyst: Xenia Musat		Sales Rep: Stefan Dreyer	
Customer Care Rep: Jessica Wagner +49 3841 360 206			

Unless otherwise agreed in writing by the parties, all sales of products and/or services in this document shall be governed solely by the applicable Honeywell Terms and Conditions in effect at the time a Purchase Order is accepted by Honeywell, a copy of which can be found at <https://aps.honeywell.com/us/en/support/safety/legal-documents/sst>. Honeywell's acknowledgment of receipt of a Purchase Order shall not constitute acceptance. By continuing with this transaction, you (Buyer) agree to those Honeywell Terms and Conditions, which are subject to change at Honeywell's discretion without notice. Honeywell expressly limits its acceptance, fulfillment and performance of this Purchase Order to the terms in the Honeywell Terms and Conditions and expressly rejects any different, conflicting or additional terms in the Purchase Order or any other Buyer documents. This sale shall be governed by the Terms and Conditions of the Honeywell legal entity listed on this document.

PRÜFBERICHT – TEST REPORT

Sauerstoffsensoren/Oxygen Sensors OOA, OOI, OOD




Kunde/ Customer	Vauda graph	Retour/ RMA- No.	300238740
Artikel/ Article	000103-2V	Anzahl/ Quantity	2
Bearbeitet/ processed	K. B. M.	Prüfdatum/ Insp. Date	13.01.23
		Geprüft/ Inspected	B. M.
		Eing. Datum/ Inc. Date	12.01.23

Produkt/ Identification			Messwert/ Test Result			Bewertung/ Evaluation		
Nr.	Seriennummer/ Serial no.	Lieferlos/ Manufact. code	Luftwert/ Air signal @ 20,9% O ₂ [mV]	Nullsignal/ Offset @ 0% O ₂ [mV]	Linearität/ Linearity [%]	Bemerkung/ Remark	außerhalb Garantie/ out of warranty	kein Fehler festgestellt/ no failure found
1	1400065	09122	0					04
2	141052	10122	8,8	23	1,0			01
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								

Fehler O2-S001: Luftwert außerhalb Toleranz/ Air signal out of tolerance
 Fehler O2-S003: Offset außerhalb Toleranz/ Offset out of tolerance
 Fehler O2-S005: Gehäuse defekt/ Housing defective

Fehler O2-S002: Signal instabil / Signal not stable
 Fehler O2-S004: Signal 0mV / Signal 0mV
 Fehler O2-S006: Elektrolyt Austritt / Electrolyte leakage



Honeywell Healthcare Solutions GmbH


✓CID4348 Opera 00007282 Type: Company Supplier Customer
Honeywell Healthcare Solutions GmbH Alter Holzhafen 18, Wismar
, D-23966, Germany

Tel 0049 3841 360204 Euro Distributor (0004)

 Log Call

Add Issue

VAT DE137437213



BOX:897

Manufacturer RMA : 300258780

☒ Repaired ☐ No Fault Found

Returned Barcode

Close File 897

Tick All Replaced

Stock Ref	Sup Ref	B/C	S/N	Fault	Replaced	No Fault Found	Repaired	Credited	Out Warranty	Returned Unrepaired	Notes
8010004		2068760	JJ140065	No Output Country of origin: Germany Customs value 5.00 euro	☐	☐	☐	☒	☐	☐	
8010004		2068844	JJ140149	High Output Country of origin: Germany Customs value 5.00 euro	☐	☐	☐	☒	☐	☐	

Update Returns

28.63
PS 2647
28.63
PS 2654

VST Returns Shipping Invoice

Delivery Address:

Honeywell Healthcare Solutions GmbH RMA: 300258780

Andre Schliemann

Alter Holzhafen 18

Wismar

Germany

D-23966

Eori DE3174778

0049 3841 360204

Date: 09 Jan 2023

VST RN: RTS3100897

Shipper Address:

VST

15 Station Road

Cross Hills

Keighley

West Yorkshire

BD20 7DT

+44 (0) 1535 634900

+44 (0) 1535 635582

info@vandagraphst.cc

Returns Under Warranty Value for Customs : 10 Euro

See Attached Listing for Serial numbers and Faults

Part Number

8010004

P/N / Value

8010004

Tariff Code: 9019209000

Description

Oxygen Sensor - R17JJ-CCR

Quantity

2

~~12A847290454503389~~

Cg 10-1-23

12A84729045455390