Service Repair Sheet SRS68404

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Marie Bray Medisafe Ltd

Service Administration Co-ordinate

01962762096

01962885777

00011608

marie.bray@medisafe.org.uk

5622

02/Mar/2023

Robert Connor

Viamed

For Calibration

Goods In Only Decontamination certificate provided by custome	
Cleaned by Viamed if no declaration certification customer Signed: 24	te 1/23
Goods Out Only	•

Signed:

Notes 28/Feb/2023 Kate Griffiths 28/Feb/2023 Kate Griffiths Would like V1000 calibrated, s/n: PR01623A14 02/Mar/2023 Robert Connor

Received 1 x V1000 s/n PR01623A14, with 4 x AA battery. Purchase order sent for 68.40 GBP, 45 GBP calibration, + 12 GBP carriage + 20 pc VAT

Ready For quote

Repair Complete Signed

CGNOON 2.3.23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35691	Foetal Simulator	1410000	PR01623A14	2

1480000 × 1 £45 S/N, SRS, SRN

1430309 X 1 FOC SIRS, SIRN

UPS x 1 R12



PURCHASE ORDER

TO:

Viamed Limited 15 Station Road Cross Hills Keighley West Yorkshire BD20 7DT

Tel: 01535 634542 Fax: 01535 635582 Please deliver to:

Medisafe Ltd Medisafe

Unit 7 Ringtower Centre Moorside Road, Winnall

Winchester Hampshire SO23 7RZ

Purchase Order Number: 5622

Purchase Order Date:

28 Feb 2023

Customer Order No:

SRS68404

QUANTITY	MODEL NO	DESCRIPTION	PART NO.	COST	SUBTOTAL
1		V1000 Foetal heart simulator for calibration SN PR01623A14		£45.00	£45.00
1 CARR	Carriage	P01000	£12.00	£12.00	
				SUBTOTAL:	£57.00
			CARRIAGE:	£0.00	
		VAT	@ 20.0%	£11.40	
				TOTAL:	£68.40

Service Repair Sheet 68404

Contact Name

Company/ Hospital Name

Position

Direct Phone

General Phone Opera Account

Email

Order Number

Date Received Booked in By Marie Bray

Medisafe Ltd

Service Administration Co-ordinator

01962762096 01962885777

00011608

marie.bray@medisafe.org.uk

5622

02/Mar/2023 Robert Connor

Repair

Ref

S/N

Equipment Type

SRN35691 1410000 PR01623A14

Foetal Simulator

Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000

Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked