



# VIAMED



FAX REF. : 7537

Page 1 of 1

DATE

7 May 1997

Jack Kimbro

UDT Sensors Inc.

12525 Chadron Ave.: Hawthorne. CA 90250 . USA

Dear Jack,


## BCI Connectors

Please see diagrams below.

We have detected a problem with the wall thickness of a DB9 when used with a BCI PulsePac Oximeter.

NB The original BCI BD9 has a thinner surrounding wall. The Nellcor has a thicker wall so if the Nellcor shell is used with BCI electrical connections it will not fit all BCI compatible products.

This is important as many small OEM's are using BCI PCB's and probes but using there own extension leads. We are trying to locate an AMP DB9 with plastic shroud to solve problem on repairs.



Kind Regards,

John S. Lamb.

**FAXED**

UDTFax 001 310 644 1727



Viamed Limited, 15 Station Road, Cross Hills,  
Keighley, West Yorkshire BD20 7DT

Tel: +44 (0) 1535 634542/636757 Fax: +44 (0) 1535 635582  
Registration No. 1291765 in England