

# Service Repair Sheet SRS68373

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Mr Mahesha

BDI India Private Limited

Customer Support

Customer Support

91802256018

00006454

mahesha@bdi-india.com

31/Jan/2023

Robert Connor

Viamed

Quote

## VIAMEDclean

### Goods In Only

Decontamination  
certificate provided  
by customer ☐

Cleaned by Viamed,  
if no declaration certificate  
from customer ☒

Signed: PK  
Date: 31/1/23

### Goods Out Only

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_  
Date: \_\_\_\_\_

Notes 24/Jan/2023 Kate Griffiths

24/Jan/2023 Kate Griffiths

Would like to end in 5 x V1000s for calibration, s/n:

MICFHS-28

MICFHS-06

MICFHS-16

MICFHS-14

MICFHS-18

31/Jan/2023 Robert Connor

Received 5 x V1000, s/n PR02380A14, PR02529A10, PR02529A12, PR02529A24, PR02540A12. 2 battery doors provided.  
not matching any unit sent.

Ready For quote

CGreen 3.2.23

\$

Repair Complete Signed

CGreen 5.4.23.

Dist.

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35627	Foetal Simulator	1410000	PR02380A14	2
SRN35628	Foetal Simulator	1410000	PR02529A10	2
SRN35629	Foetal Simulator	1410000	PR02529A12	2
SRN35630	Foetal Simulator	1410000	PR02529A24	2
SRN35631	Foetal Simulator	1410000	PR02540A12	2

1480000 x 5 \$46.75  
S/N, SRS, SRN

1430296 x 4 \$1.80  
SRS, SRN

1430309 x 5 -FOC  
SRS, SRN

1430286 x 1 - SRN 35628 \$3.10  
SRS, SRN

UPS 31x31x25cm  
3.50kg

1430284 x 4 \$37.18  
SRS, SRN



## Packing Slip

DATE 24-Jan-23		Packing Slip No: PS-2301-01				
SHIPPER/ EXPORTER BDI India Private Limited "Shreeshyla", Doddakallasandra, Kanakapura Road, Bangalore 560 062 INDIA  TEL. NO. +91-80-22560418/19		CONSIGNEE (Complete name & Address) Viamed Ltd Repairs Team SRS68345 15 Station Road Cross Hills Keighley BD20 7DT West Yorkshire United Kingdom Attn: Kate Griffiths Tel: +44 (0)1535 634542				
COUNTRY OF EXPORT UK		IMPORTER IF OTHER THAN CONSIGNEE Viamed Ltd Repairs Team SRS68345 15 Station Road Cross Hills Keighley BD20 7DT West Yorkshire United Kingdom				
COUNTRY OF ORIGIN OG GOODS India		Proforma Invoice # PI2301-01 & Date: Dt 24.01.2023				
Country of Ultimate Destination UK						
Mark/No	No. of Packages	Complete Description of Goods	QTY in Nos	Net Weight	Gross Weight	Remarks
	1	Foetal Heart Simulator ✓ PR02380A12 90181990 ✓ PR02529A10 90181990 ✓ PR02529A24 90181990 ✓ PR02529A12 90181990 ✓ PR02540A12 90181990	1 1 1 1 1	2	2.5	Dimension of box cm-31 X 25 X 24
<b>"Supply Meant for Export Under LUT without Payment of IGST"</b> LUT ARN No. AD290322034223I Dt.31/03/2022						
Total No of Pkgs. 1 pkg					Total Weight 2.5 Kgs	Kgs Kgs
<b>"Supply Meant for Export Under LUT without Payment of IGST"</b> LUT ARN No. AD290322034223I Dt.31/03/2022 IEC # 0707004101 AD Code # 6500120 The shipment under Duty free Commercial Scheme without Benefit						
SIGNATURE OF SHIPPER (Name, Title & Signature)				24-01-2023 DATE		



PR-02380 A14

Service Repair Sheet 68373

Contact Name	Mr Mahesha
Company/ Hospital Name	BDI India Private Limited
Department	Customer Support
Position	Customer Support
Direct Phone	91802256018
Opera Account	00006454
Email	mahesha@bdi-india.com
Order Number	BDI/Viamed/PO/2302-01/2023
Date Received	31/Jan/2023
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	
SRN35627	1410000	PR02380A14	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309

V1000 has had transducer interface cushion replaced and calibration has been checked

---

Repair	Ref	S/N	Equipment Type	
SRN35628	1410000	PR02529A10	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309
Qty: 1	1430286
Qty: 1	1430284
Qty: 1	1430296

V1000 has had transducer interface cushion, lower case and seal replaced and calibration has been checked

---

Repair	Ref	S/N	Equipment Type	
SRN35629	1410000	PR02529A12	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309
Qty: 1	1430284
Qty: 1	1430296

V1000 has had transducer interface cushion and lower case replaced, calibration has been checked

---

Service Repair Sheet 68373  
Contact Name Mr Mahesha  
Company/ Hospital Name BDI India Private Limited  
Department Customer Support  
Position Customer Support  
Direct Phone 91802256018  
Opera Account 00006454  
Email mahesha@bdi-india.com  
Order Number BDI/Viamed/PO/2302-01/2023  
Date Received 31/Jan/2023  
Booked in By Robert Connor

---

Repair	Ref	S/N	Equipment Type	
SRN35630	1410000	PR02529A24	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309
Qty: 1	1430284
Qty: 1	1430296

V1000 has had transducer interface cushion and lower case replaced, calibration has been checked

---

Repair	Ref	S/N	Equipment Type	
SRN35631	1410000	PR02540A12	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309
Qty: 1	1430284
Qty: 1	1430296

V1000 has had transducer interface cushion and lower case replaced, calibration has been checked

---