



Janine Gill &lt;viamed.janine.gill@gmail.com&gt;

---

**Fwd: Teledyne Sensor Error**

---

**Main Account** <office@viamed.co.uk>  
To: Janine Gill <janine.gill@vmsecure.me.uk>

14 April 2023 at 10:33

----- Forwarded message -----

From: **Daniel Lodge** <[Daniel.Lodge@liverpoolft.nhs.uk](mailto:Daniel.Lodge@liverpoolft.nhs.uk)>  
Date: Fri, 14 Apr 2023 at 10:31  
Subject: Teledyne Sensor Error  
To: [orders@viamed.co.uk](mailto:orders@viamed.co.uk) <[orders@viamed.co.uk](mailto:orders@viamed.co.uk)>

Hello,

We have a AX300 with the serial number 339155 that keeps showing the alarm sensor and showing zero, the O2 sensor has been changed but to no avail. The product is no longer under warranty I have been told so was wondering if you could please send a quote for the cost of the repair of the unit.

Kind Regards,  
Daniel

**Daniel Lodge**  
Senior Medical Engineer

Liverpool University Hospital's NHS Foundation Trust

T: 0151 706 2079  
E: [daniel.lodge@liverpoolft.nhs.uk](mailto:daniel.lodge@liverpoolft.nhs.uk)

Medical Engineering Department | Royal Site | Liverpool University Hospital's NHS Foundation Trust | Mount Vernon Street | Liverpool | L7 8YE