28/04/2023, 10:40 Gmail - Re: FW: P.O. 2858

Please consider the environment. Do you really need to print this e-mail?

This e-mail and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed.

If you have received this e-mail in error please notify the originator of the message.

If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful.

From: Main Account <viamedinbox@gmail.com> On Behalf Of Ryan Swaine

Sent: Monday, April 24, 2023 11:54 AM To: Info Cortessis <info@cmedical.gr>

Subject: Re: Device defective

Dear Vagelis

There are no compatibility issues between the VM-2160 SMARTsat, but you can not add a PCB from the original none SMARTsat to a SMARTsat version.

The SMARTsat models have SMARTsat printed on the front above the display.

We have 2x 0039028 available from stock, we would just need a few days to programme them.

Best regards

Ryan

Ryan Swaine International Sales Manager **VIAMED**

www.viamed.co.uk

Email: ryan.swaine@viamed.co.uk Office: +44 (0) 1535 634542

Mobile: +44 (0) 7803 907117

GDPR / Privacy Policy available at www.viamed.co.uk/policy

On Mon, 24 Apr 2023 at 09:48, Info Cortessis <info@cmedical.gr> wrote:

Dear Ryan,

Thank you very much for your reply. Our service department would like to know if there are different versions of Smartsat models, with incompatibilities among those different versions and if that's true then how can we differentiate them using the S/N?