

## Procedures for Converting the R-33S1 Sensors into the WGA-01

WGA-01 is used in the following instruments:

- Weld Wide Ar-Gone
  - Sumner Ar-Gone
- 
- 1) Change the polarity of the R-33S1 sensor
  - 2) Provide Derek with the barcodes of the R-33S1 sensors. Inform Derek of the Model (WGA-01) and the company name to be on the sensor (Weld Wide or Sumner).
  - 3) Remove original Teledyne label and replace with new OEM label.
  - 4) Sensors to be given to Steve Nixon for fitting into instruments.

vm3COP 40.43