

CID5540 Opera V005212 Type:Vandagraph Trade

Italgoods Via Giacomo Matteotti 1, Arese (MI), , , 20020, Italy

Tel 0039 0293586544 GBP Trade Price List Vandagraph (0009)

Credit 30 Days after date of invoice Credit Limit 0.00GBP

VAT IT04048470969

Log Call

Add Issue

Account Home

Main Details

Account Memos

Sales History

Stock References

Cust./Supp. Returns

Service Visits

Distributor Agreements

Documents Files

Linked Issues

Regulatory Agreements

Guido pays with a temporary one time CC number. Upon receiving an order, give him the total price and he will issue card details for one transaction only - RS 06/05/2020

Individual Packed Sensors - RS 05/05/20

New address added 15/06/2020 RS

Use UPS - RS 05/05/20

SRS68472

SRS Created : 16 May 2023
Created By Robert Connor
Add Watch

[Print Barcodes](#)
[Print A4 Sheet](#)
[Split Items into Different SRS Numbers](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description

Choose a file to upload:

Choose file

No file chosen

Next

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock

Unopened - will apply to all items on srs

☐ Clear From System - Force from System.

- will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68472		Notes	
Company / Hospital	Italgoods	16/May/2023 Robert Connor	
Contact Name	Guido Lapucci	16/May/2023 Robert Connor	
Department		Returned 2 x mixchek;	
Position		277937 for repair,	
Company Phone	0039 0293586544	248557 for calibration.	
Direct Phone		LINKED ISSUE NOTES:	
Opera Account	V005212	296050:	
Email	info@italgoods.com	AutoGenerated Issue SRS68472 Appears to be Complete	
Order Number			
Viamed ORD Number			
Date Received Into building	16 May 2023		
Type	Quote Before Repair		
	Move to Repair		

Issues?	296050									
Items for Repair										
... ..										
SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN35794	MixChek	MIXCHEK	 298426	277937	Mixchek	No	No	Complete - Repaired 24 May 2023 Michael Green	Calibration Problem	01:00
SRN35794 Engineer Notes: INTERNAL NOTES not for customer discussion 24/May/2023 Michael Green The Mixchek analyser has been serviced. The R-33S1 Oxygen sensor has been replaced with SN:928898. The gas sample tubing has been replaced. The unit has been calibrated.										
SRN35795	MixChek	MixChek	 248557	248557		No	No	Complete - Repaired 24 May 2023 Michael Green	Calibration Problem	01:00
SRN35795 Engineer Notes: INTERNAL NOTES not for customer discussion 24/May/2023 Michael Green The Mixchek analyser has been serviced. The R-33S1 Oxygen sensor has been replaced with SN:928899. The unit has been calibrated.										

Currently Viewing ITEM SRN35794 MixChek MixChek 248557

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Mixchek analyser has been serviced. The R-33S1 Oxygen sensor has been replaced with SN:928899. The unit has been calibrated.	24/May/2023 Michael Green The Mixchek analyser has been serviced. The R-33S1 Oxygen sensor has been replaced with SN:928899. The unit has been calibrated.	The Mixchek analyser has been serviced. The R-33S1 Oxygen sensor has been replaced with SN:928899. The unit has been calibrated.

-