

Service Repair Sheet SRS68486

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Terry Millen

University Hospital Crosshouse

Medical Physics Department

01563826080

01563 21133

00001320

terry.millen2@aapct.scot.nhs.uk

07/Jun/2023

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 06/Jun/2023 Steve Hardaker

06/Jun/2023 Steve Hardaker

Returning a high-flow MaxBlend for repair, s/n TE00000034, the reed valve is not alarming.

I have asked Jim at Maxtec whether the parts are still available or if these can be repaired and serviced with MaxBlend 2 parts.

07/Jun/2023 Robert Connor

Received 1 x Maxblend s/n TL00000034, with MAX250E s/n FG40399059, plus flow diverter.

Ready For quote

CGreen 9.6.23

Repair Complete Signed _____

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35818	Blender		TL00000034	2
SRN35819	Oxygen Sensor	0110429	FG40399059	2

0380061 x 1 @ £180
SIN, SRS, SRN

R200P02 x 1 @ £270
SRS, SRN

~~0110429 x 1 @ £69~~ 0140012
~~0140012~~ x 1 @ £0 C
old SIN, SRS, SRN.

0110429 x 1 @ £69 amended
cg 9.6.23.
NEW SIN, SRS, SRN

UPS x 1 @ £12.