



Peter Wilkinson

 CID20392 Opera CID20392 Type:Vandagraph Retail

Peter Wilkinson 122 Houghton Road, , Dunstable, , LU5 5AE, UK

Tel **07966 261587** GBP Retail Price List Vandagraph (0010)

 Log Call

Add Issue

Proforma Credit Limit 0.00GBP

 Account Home

 Main Details

Account Memos

 Sales History

Stock References

🔄 Cust./Supp. Returns

 Service Visits

Distributor Agreements

Documents
Files

Linked Issues

Regulatory Agreements

SRS68482

SRS Created : 02 Jun 2023

Created By Ryan Swaine

Add Watch

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

Handle with care

Add Items to Supplier Returns Box

Add

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Service Repair Sheet 68482		Notes
Company / Hospital	Peter Wilkinson	02/Jun/2023 Ryan Swaine
Contact Name	Peter Wilkinson	02/Jun/2023 Ryan Swaine
Department		R-33S1 recently purchased, fitted to Mixchek 1 month ago. Calibrated to air okay, but gives O2 reading of 30% in 18%O2. Test sensor and replace if faulty. If no fault found, then suggest to client we need to take a look at the MixChek.
Position		Mixchek had previously been in contact with salt water, but we cleaned it and got it working.
Company Phone	07966 261587	08/Jun/2023 Robert Connor
Direct Phone	07966 261587	Received 1 x mixchek s/n 250601, with metal tee.
Opera Account	CID20392	
Email	peter.wilkinson1966@gmail.com	
Order Number		LINKED ISSUE NOTES:
Viamed ORD Number		298123 : AutoGenerated Issue SRS68482 Appears to be Complete
Date Received Into building	08 Jun 2023	298124 : AutoGenerated Issue SRS68482 Appears to be Complete
Issues?	298123 298124	

Items for Repair

...

SRN	Equipment	Stock Reference	Barcode	SerialNumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN35823	MixChek	MIXCHEK	 86957	250601	Mixchek	No	No	Complete - Repaired 16 Jun 2023 Michael Green	Calibration Problem	00:00
SRN35823 Engineer Notes: INTERNAL NOTES not for customer discussion 16/Jun/2023 Michael Green The Mixchek analyser has been tested. The Oxygen sensor has an unstable output. 16/Jun/2023 Michael Green The Mixchek analyser has had a new Oxygen sensor fitted under warranty. The gas sample tubing has been replaced. 16/Jun/2023 Michael Green New R-33S1 SN:928902										

Currently Viewing ITEM SRN35823 MixChek MIXCHEK 250601 Mixchek

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Mixchek analyser has had a new Oxygen sensor fitted under warranty R-33S1 SN:928902. The gas sample tubing has been replaced.	16/Jun/2023 Michael Green The Mixchek analyser has been tested. The Oxygen sensor has an unstable output. 16/Jun/2023 Michael Green The Mixchek analyser has had a new Oxygen sensor fitted under warranty. The gas sample tubing has been replaced. 16/Jun/2023 Michael Green New R-33S1 SN:928902	The Mixchek analyser has had a new Oxygen sensor fitted under warranty R-33S1 SN:928902. The gas sample tubing has been replaced.

-